

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Adhex Technologies 231128 M. Franck Leborne 44 Rue de Longvic 21300 Chenôve France +33 6 21 31 68 54 f.leborne@adhex.com
--	---

Preventive reference number	PMREPORT-224_PM821_2025-02-19
Contract number / Numéro de contrat	CM1911023
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	FS330.01
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 330 CP / 318X-0.1388
SN:WA:	34.630
Installation date of material:	

TECHNICAL DATAS

PC MODEL	OptiPlex 7040 / Tag 13GS7J2
PC NAME	TubeScan-PC
ADDITIONAL CAMERA INFO	TubeScan DS 330 CP / 318X-0.1388
OPERATION SYSTEM	Windows 10 Pro / 2016
MEMORY RAM	8 GB
FREE SPACE ON C	415 / 453 GB
FREE SPACE ON D	-
TEAMVIEWER ID	1 535 846 570 / v12
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.2.78.116
UPG OR DNG VERSION DURING MAINTENANCE	7.2.81.120

Start time PM:	19/02/2025 13:30
End time PM:	19/02/2025 15:30

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	
View monitor resolution		1920x1080	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓				
PC's fans ?	⏸				
PC's filter	⏸		Installation date:		
Lens cleaning	✓	Looking up			
Mirror cleaning	✓		Softwareworkflowcommunication	⏸	
Backing or RRB cleaining	✗	Scratched	Check Teamviewer access	✓	Via Dongle Wifi USB
Lens Focal	✓		Calibration of camera detail & 100%camera	⏸	
Camera alignment with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✗		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓ ENCODER WHEEL:: 2RDHO234275
- ✓ LED Board equipped V40 L=140mm: 1ELLT256485
- ✓ LED Board equipped V40 L=160mm: 1ELLT256486
- ✓ ENCODER'S SPRING
- ✓ BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)


(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Done. Need to replace the Backplate asap.

Customer signature:

Name:

Date :


mercredi 19 février 2025 15:01:27

BST eltromat FRANCE signature:

Name:

Date :


mercredi 19 février 2025 14:43:28

ATTACHED PM'S FILE(S)

Picture 19022025	Screenshot 19022025
	