

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	DS Smith (Contoire-Hamel) xxx M. Stéphane Ryckebusch 39 rue Nationale 80500 Contoire-Hamel France +33 7 88 98 25 49 stephane.ryckebusch@dssmith.com
--	--

Preventive reference number	PMREPORT-18_PM568_2023-11-29
Contract number / Numéro de contrat	CM2012036
Contract date:	2021/12/01 -> 2024/11/30
Machine customer name:	Cobden Chadwick
Assign to:	CouV
Material:	VIDEO_IPQ_Center
SN:WA:	ASO092491_WA0021320
Installation date of material:	2023/02/06

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE04.2-7-A
PC NAME	21320-IPQ-1
ADDITIONAL CAMERA INFO	IPQ Center
OPERATION SYSTEM	Windows 10 pro
MEMORY RAM	64 gb
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	1 649 168 535
IP ADDRESS EXTERN FOR INTERNET	192.168.1.21
ORIGINAL VERSION	
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touchmonitorcalibration	NA		Ipqchecksynchronization	NA	
Pscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	OK	
Pscreenresolutionview		1920x1080	Ipqencoderwheelstatus	OK	
Hardwareconditionscrews	OK		Ipqencoderwheelrunningonweb	OK	
Hardwareconditioncables	OK		Alarmstatusindicator	OK	
Hardwareconditionconnectors	OK		Upsbatteryexchanged	NA	
Digitalcheckfan	OK		Upsdatebatteryexchanged		UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	OK		Installation date:		2023-02-06
Traversecamera	OK		Upscommunicationchecking	OK	
Traversecameralenscleaning	OK		Softwareupdate	NA	
Traversewscamerareplaceflashbulb	NA		Version upgraded		
Traversewscameracleanwindows	OK		Softwareipqtcu		8.6
Camerachangefiltercheckfan	OK		Softwareipqwsc		no
Traversewscamerashadowreducingbackplate	NA		Softwareipqpps		no
Traversewscameracheckflashbulblackerflash	OK		Softwareipqli		no
Traversewscameracheckcleanmirrorlackercamera	OK		Softwareworkflowcommunication	OK	
Traversewscameracheckzoomirisfocuswscboard	OK		Softwareremote	OK	
Traversewscameracalibrationzoomirisfocus	NA		Operatorinstructions	NA	
Traversebackflash	NA		Backupscreenshots	OK	
Traversebackflashflashbulb	NA		Backupimage	NA	
Linecameracleanmirror	OK		Backupsoftware	NA	
Led checking+reflector checking+dome	OK				
Linecameramechanicalcheck	OK				
Linecamerabacklightmechanicalcheckjigs	NA				
Camera mechanicalalignementtoprint	OK				
Camera whitecalibration	NA				

Customer_comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator and update your navigator)

calibration of the 100% camera needs to be done every years due to excessive vibration of the machine. The matrix camera has a shade on the top of the picture.

Customer signature:

BST eltromat FRANCE signature:

