

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	DB Technique F-1555 M. Sylvain Grand 547 rue de la Bergeresse, 45160 Olivet France +33 6 20 50 04 08 sylvain.grand@dbtechnique.fr
--	--

Preventive reference number	PMREPORT-26_PM578_2023-12-13
Contract number / Numéro de contrat	CM1912026
Contract date:	2023/11/01 -> 2024/10/31
Machine customer name:	Sirius 1
Assign to:	CouV
Material:	VIDEO_Tubescan_DS
SN:WA:	38.809
Installation date of material:	2018/02/13

TECHNICAL DATAS

PC MODEL	Please fill system information
PC NAME	TUBESCAN38809
ADDITIONAL CAMERA INFO	TubeScan DS 330 4K / BF3-M2-00833
OPERATION SYSTEM	Windows 10 pro
MEMORY RAM	16 gb
FREE SPACE ON C	189 gb
FREE SPACE ON D	
TEAMVIEWER ID	602 659 423 / v12
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.29.78
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touch monitor calibration	KO	The touchscreen is not responding to touch	Fixation encoder	OK	
Touch monitor resolution		1024x768	Encoder wheel status	OK	the wheel needs to be replaced
View monitor resolution		1920x1080	Encoder wheel on web?	OK	
Fixation screws of system?	OK		Spring(s) encoder status ?	OK	
Cables status ?	OK		Alarm Indicator status ?	NA	
Connectors cameras (well tight?)	OK				
PC's fans ?	NA				
PC's filter	NA		Installation date:		2018-02-13
Lens cleaning	OK				
Mirror cleaning	OK		Software workflow communication	NA	
Backing or RRB cleaning	OK		Check Teamviewer access	NA	
Lens Focal	NA		Calibration of camera detail & 100% camera	NA	
Camera alignment with printing	OK		Operators instruction ?	OK	
Check web under camera	OK	The camera had to be moved to have a stable web	Screenshots	OK	
Height compensator calib	OK		ACRONIS ?	NA	
Encoder offset calib	NA		Backup application	OK	
Only with EV- LED calibrations	NA				
Kisspoint only with 2 cameras	NA				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

	ENCODER WHEEL:: 2RDHO234275
	LED Board equipped V40 L=140mm: 1ELLT256485
	LED Board equipped V40 L=160mm: 1ELLT256486
	ENCODER'S SPRING
	BACKPLATE W/B

Customer_comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

L'écran tactile ne réponds presque plus au toucher.

La position de la caméra a été ajustée pour avoir un passage de matières stable.

Customer signature:

BST eltromat FRANCE signature:



BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	DB Technique F-1555 M. Sylvain Grand 547 rue de la Bergeresse, 45160 Olivet France +33 6 20 50 04 08 sylvain.grand@dbtechnique.fr
--	--

Preventive reference number	PMREPORT-25_PM576_2023-12-13
Contract number / Numéro de contrat	CM1912026
Contract date:	2023/11/01 -> 2024/10/31
Machine customer name:	C4R+
Assign to:	CouV
Material:	VIDEO_Tubescan_DS
SN:WA:	ASO075195 _ 42.1752
Installation date of material:	2021/05/11

TECHNICAL DATAS

PC MODEL	OptiPlex 7080
PC NAME	TUBESCAN421752
ADDITIONAL CAMERA INFO	Tubescan DS 330 4K / M2089aC-0.0833
OPERATION SYSTEM	Windows 10 pro
MEMORY RAM	16 gb
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	1 089 264 771 / v12
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.57.2097
UPG OR DNG VERSION DURING MAINTENANCE	7.4.57.2097

	COMMENTS		COMMENTS
Touch monitor calibration	NA	Fixation encoder	OK
Touch monitor resolution	1024x768	Encoder wheel status	OK
View monitor resolution	1920x1080	Encoder wheel on web?	OK
Fixation screws of system?	OK	Spring(s) encoder status ?	OK
Cables status ?	OK	Alarm Indicator status ?	NA
Connectors cameras (well tight?)	OK		
PC's fans ?	NA		
PC's filter	NA	Installation date:	2021-05-11
Lens cleaning	OK		
Mirror cleaning	OK	Software workflow communication	NA
Backing or RRB cleaning	OK	Check Teamviewer access	OK
Lens Focal	NA	Calibration of camera detail & 100% camera	NA
Camera alignment with printing	OK	Operators instruction ?	OK
Check web under camera	OK	Screenshots	OK
Height compensator calib	OK	ACRONIS ?	NA
Encoder offset calib	OK	Backup application	OK
Only with EV- LED calibrations	NA		
Kisspoint only with 2 cameras	NA		

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

☐	ENCODER WHEEL:: 2RDHO234275
☐	LED Board equipped V40 L=140mm: 1ELLT256485
☐	LED Board equipped V40 L=160mm: 1ELLT256486
☐	ENCODER'S SPRING
☐	BACKPLATE W/B

Customer_comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Le contour light ne s'allume plus, la carte n'envoie plus de 24V.

La batterie de l'onduleur est HS et doit être remplacée.

L'application a été mise a jour.

Customer signature:

BST eltromat FRANCE signature:



BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elxis.group/	DB Technique F-1555 M. Sylvain Grand 547 rue de la Bergeresse, 45160 Olivet France +33 6 20 50 04 08 sylvain.grand@dbtechnique.fr
--	--

Preventive reference number	PMREPORT-27_PM579_2023-12-13
Contract number / Numéro de contrat	CM1912026
Contract date:	2023/11/01 -> 2024/10/31
Machine customer name:	Sirius 2
Assign to:	CouV
Material:	VIDEO_Tubescan_DS
SN:WA:	38.948
Installation date of material:	2018/07/16

TECHNICAL DATAS

PC MODEL	Optiplex 3050
PC NAME	TBUESCAN38948
ADDITIONAL CAMERA INFO	TubeScan DS 330 4K / BF3-M2-0.0833
OPERATION SYSTEM	Windows 10 pro
MEMORY RAM	16 gb
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	1 166 728 592 / v12
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.29.78
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

	COMMENTS		COMMENTS
Touch monitor calibration	NA	Fixation encoder	OK
Touch monitor resolution	1024x768	Encoder wheel status	OK Replacement is advised
View monitor resolution	1920x1080	Encoder wheel on web?	OK
Fixation screws of system?	OK	Spring(s) encoder status ?	OK
Cables status ?	OK	Alarm indicator status ?	NA
Connectors cameras (well tight?)	OK		
PC's fans ?	NA		
PC's filter	NA	Installation date:	2018-07-16
Lens cleaning	OK		
Mirror cleaning	OK	Software workflow communication	NA
Backing or RRB cleaning	OK	Check Teamviewer access	OK
Lens Focal	NA	Calibration of camera detail & 100% camera	NA
Camera alignment with printing	OK	Operators instruction ?	OK
Check web under camera	KO The web is doing wave because the roll of the Sirius were not aligned. The rolls of the machine were adjusted. Testing was not possibl due to production	Screenshots	OK
Helght compensator calib	NA	ACRONIS ?	NA
Encoder offset calib	NA	Backup application	OK
Only with EV- LED calibrations	NA		
Kisspoint only with 2 cameras	NA		

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| 1 | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

Customer_comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Une barre LED est HS cela peut causer des problèmes de détection sur les matières brillantes.

Customer signature:

BST eltromat FRANCE signature:

