

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Helios Sa (Lessay) 301107 M. Dupray Sebastien 43 Route de la ZI 50430 Lessay France +33 2 33 17 13 13 sdupray@helios-imp.com
--	---

Preventive reference number	PMREPORT-19_PM570_2023-11-29
Contract number / Numéro de contrat	CM1912027
Contract date:	2023/02/01 -> 2026/01/31
Machine customer name:	Biva 2 - CI12894
Assign to:	RelR
Material:	VIDEO_IPQ_Center
SN:WA:	WA19168
Installation date of material:	2015/12/01

TECHNICAL DATAS

PC MODEL	IPC-BG-R7910/BSTE01.0
PC NAME	19168IPQ-Center-1-1
ADDITIONAL CAMERA INFO	IPQ Center
OPERATION SYSTEM	WINDOWS EMBEDDED Standard
MEMORY RAM	32Go
FREE SPACE ON C	81.2GB
FREE SPACE ON D	103GB
TEAMVIEWER ID	715 893 972 / v12
IP ADDRESS EXTERN FOR INTERNET	192.168.55.21 255.255.255.0 192.168.55.3 DNS:192.168.55.6
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touchmonitorcalibration	OK		Ipqchecksynchronization	OK	
Pscreenresolutiontouch		1920X1080	Ipqencoderwheelfixing	OK	
Pscreenresolutionview		1920X1080	Ipqencoderwheelstatus	OK	
Hardwareconditionscrews	OK		Ipqencoderwheelrunningonweb	OK	
Hardwareconditioncables	OK		Alarmstatusindicator	OK	
Hardwareconditionconnectors	OK		Upsbatteryexchanged	NA	
Digitalcheckfan	OK		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	OK		Installation date:		2015-12-01 -> 07 YEAR(S)
Traversecamera	OK		Upscommunicationchecking	OK	
Traversecameralenscleaning	OK		Softwareupdate	NA	
Traversewscamerareplaceflashbulb	NA		Version upgraded		
Traversewscameracleanwindows	OK		Softwareipqtcu		1.12
Camerachangefiltercheckfan	OK		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	OK		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	NA		Softwareipqli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	NA		Softwareworkflowcommunication	OK	
Traversewscameracheckzoomirisfocuswscboard	OK		Softwareremote	OK	
Traversewscameracalibrationzoomirisfocus	OK		Operatorinstructions	NA	
Traversebackflash	NA		Backupscreenshots	NA	
Traversebackflashflashbulb	NA		Backupimage	NA	
Linecameracleanmirror	OK		Backupsoftware	OK	
Led checking+reflector checking+dome	OK				
Linecameramechanicalcheck	OK				
Linecamerabacklightmechanicalcheckjigs	OK				
Camera mechanicalalignementtoprint	OK				
Camera whitecalibration	OK	Besoin de commandé nouvelle plaque calibration alignement et blancs.			


Customer_comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator and update your navigator)

Customer signature:

BS

T eltromat FRANCE signature:



Richard Relin 2023-11-30T17:24:36+01:00



Stephane Aubril 2023-11-30T15:07:27+01:00