

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CCL Package Label - Pharma (Chilly-Mazarin) ACU231910 M. Jean-Charles Campana 20 Avenue Arago 91380 Chilly-Mazarin France +33 7 63 04 72 66 jccampana@cclind.com
--	---

Preventive reference number	PMREPORT-281_PM905_2025-06-04
Contract number / Numéro de contrat	CM1708005
Contract date:	2022/01/01 -> 2024/12/31
Machine customer name:	Presse 443
Assign to:	NguJ
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 430 4K / M2089aC0.1111
SN:WA:	ASO071778_42.1585
Installation date of material:	

TECHNICAL DATAS

PC MODEL	5070
PC NAME	TUBESCAN421585
ADDITIONAL CAMERA INFO	TubeScan DS 430 4K / M2089aC0.1111
OPERATION SYSTEM	Windows 10 pro
MEMORY RAM	16 gb
FREE SPACE ON C	159 gb
FREE SPACE ON D	
TEAMVIEWER ID	631 030 314 / v12
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.44.111
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	04/06/2025 15:47
End time PM:	

COMMENTS			COMMENTS		
Touch monitor calibration	II		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	clean the wheel
View monitor resolution		1920x1080	Encoder wheel on web?	✗	printer put the encoder wheel on the side of machine not on the web
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓	cabling pull on 24V, it is critical	UPS battery exchanged ?	✗	
PC's fans ?	II		Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommand to exchange every 5 years.
PC's filter	II		Installation date:		-> 00 YEAR(S)
Lens cleaning	✓		UPS communication?	✗	COMUNICATION OK MUST CHANGE BATTERY ALERT ON UPS
Mirror cleaning	✓		Softwareworkflowcommunication	II	
Backing or RRB cleaning	II		Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100%camera	II	
Camera alignment with printing	II		Operators instruction ?	II	
Check web under camera	II		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	II	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	II				
Kisspoint only with 2 cameras	II				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

- ✅: Checked, nothing to report / Vérifié, RAS
❌: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :


04/06/2025 16:58

BST eltromat FRANCE signature:

Name:

Date :


04/06/2025 16:57

ATTACHED PM'S FILE(S)

screenshots	photos	mechanical modification for web touche RBB
		