

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Adhex Technologies 231128 M. Franck Leborne 44 Rue de Longvic 21300 Chenôve France +33 6 21 31 68 54 f.leborne@adhex.com
--	---

Preventive reference number	PMREPORT-220_PM817_2025-02-18
Contract number / Numéro de contrat	CM1911023
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	Alpha 250
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 250 4K / M2089aC0.0833
SN:WA:	ASO083905_42.2112
Origin BST France order:	212586
Installation date of material:	2022/03/14

TECHNICAL DATAS

PC MODEL	OptiPlex 7090 / Tag 8Y420L3
PC NAME	TubeScan422112
ADDITIONAL CAMERA INFO	TubeScan DS 250 4K / M2089aC0.0833
OPERATION SYSTEM	Windows 10 Pro / v21H1
MEMORY RAM	16 GB
FREE SPACE ON C	78.4 / 237 GB
FREE SPACE ON D	-
TEAMVIEWER ID	916 669 771 / v15
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.48.116
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	18/02/2025 13:30
End time PM:	18/02/2025 15:30

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	
View monitor resolution		1920x1080	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓	Rewiring	Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓				
PC's fans ?	II				
PC's filter	II		Installation date:		2022-03-14
Lens cleaning	✓	Looking up			
Mirror cleaning	✓		Softwareworkflowcommunication	✓	QLink
Backing or RRB cleaining	✓		Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100%camera	II	
Camera alignment with printing	✓		Operators instruction ?	II	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	II	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	II				
Kisspoint only with 2 cameras	II				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓ ENCODER WHEEL:: 2RDHO234275
- ✓ LED Board equipped V40 L=140mm: 1ELLT256485
- ✓ LED Board equipped V40 L=160mm: 1ELLT256486
- ✓ ENCODER'S SPRING
- ✓ BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Done - UPS was disconnected between the PMs

Customer signature:

Name:

Date :


mardi 18 février 2025 16:40:44

BST eltromat FRANCE signature:

Name:

Date :


mardi 18 février 2025 16:41:11

ATTACHED PM'S FILE(S)

Picture 18022025	Screenshot 18022025
	