

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CCL Package Label - Pharma (Chilly-Mazarin) ACU231910 M. Jean-Charles Campana 20 Avenue Arago 91380 Chilly-Mazarin France +33 7 63 04 72 66 jccampana@cclind.com
--	---

Preventive reference number	PMREPORT-279_PM903_2025-06-04
Contract number / Numéro de contrat	CM1708005
Contract date:	2022/01/01 -> 2024/12/31
Machine customer name:	Presse 445
Assign to:	NguJ
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 430 4K / M2089aC 0.1111
SN:WA:	ASO104166_50.2873
Origin BST France order:	242027
Installation date of material:	2024/10/31

TECHNICAL DATAS

PC MODEL	OptiPlex SFF 7010
PC NAME	Tubescan502873
ADDITIONAL CAMERA INFO	TubeScan DS 430 4K / M2089aC 0.1111
OPERATION SYSTEM	Windows 10 Pro / 22H2
MEMORY RAM	16 GB
FREE SPACE ON C	135 / 238 GB
FREE SPACE ON D	-
TEAMVIEWER ID	
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.57.20297
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	04/06/2025 12:42
End time PM:	

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	ADJUST SPRING TO HAVE MORE TENSION
Touch monitor resolution		1920x1080	Encoder wheel status	✓	
View monitor resolution		1920X1080	Encoder wheel on web?	✗	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	24V WAS CONFIGURE FOR EXTERNAL USE - REWIRED CONNECTION
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✗	
PC's fans ?	⏸		Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommend to exchange every 5 years.
PC's filter	⏸		Installation date:		2024-10-31 -> 00 YEAR(S)
Lens cleaning	⏸	DIFFICULT ACCESS BUT CAMERA IS HORIZONTAL POSITION SO NO DUST ON LENS	UPS communication?	✓	
Mirror cleaning	⏸		Software workflow communication	⏸	
Backing or RRB cleaning	✗	BACKPLATE IS DEFECTIVE NEED TO REPLACE ONE	Check Teamviewer access	✗	NO NETWORK CABLE
Lens Focal	⏸		Calibration of camera detail & 100% camera	⏸	
Camera alignment with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	

Only with EV- LED calibrations		
Kisspoint only with 2 cameras		

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

- : Checked, nothing to report / Vérifié, RAS
: Not OK, checked comment / Pas OK, vérifiez commentaires
: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :


04/06/2025 16:48

BST eltromat FRANCE signature:

Name:

Date :


04/06/2025 16:46

ATTACHED PM'S FILE(S)

[original- wiring is set now](#)



[photos](#)



[screenshots](#)

