

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Tilwel 231461 Noel GENET 115 Rue du Closeau 77170 Brie-Comte-Robert France +33 1 60 62 51 20 Noel.GENET@tilwel.fr
--	--

Preventive reference number	PMREPORT-320_PM946_2025-08-27
Contract number / Numéro de contrat	CM2501079
Contract date:	2025/03/01 -> 2027/02/28
Machine customer name:	BOBST
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO094807_WA22411
Origin BST France order:	222453
Installation date of material:	2023/05/15

CUSTOMER ORDER:	CDE CLIENT CATIL2500570
-----------------	-------------------------

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE03.1-3
PC NAME	22411-IPQ-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise LTSC - 2018
MEMORY RAM	64.0 GB
FREE SPACE ON C	42.8 / 75.1 GB
FREE SPACE ON D	F:\ 7.25 / 7.27 TB
TEAMVIEWER ID	1 677 290 776 / v15
IP ADDRESS EXTERN FOR INTERNET	IP Address : 192.168.2.105 Subnet mask : 255.255.255.0 Defaut gateway : 192.168.2.238 Default DNS server : 192.168.1.202 Alt DNSserver : 192.168.1.203
ORIGINAL VERSION	3.1
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	27/08/2025 10:00
End time PM:	27/08/2025 15:00

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✓	Origin
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2023-05-15 -> 02 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✓	8 Flash Bulbs	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.13
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqjli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	⏸	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	ID 1 677 290 776
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	✓	ipq-center_bak_2025_08_27_11_25_52
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Cameramechanicalalignementtoprint	✓				
Camerawhitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Done

- 8 Flash Bulbs replaced
- BC grading OK

Customer signature:

Name:

Date :




BST eltromat FRANCE signature:

Name:

Date :



ATTACHED PM'S FILE(S)

Offre_PR 250605-0418 	CDE CLIENT CATIL2500570 	Picture 27082025 	Screenshot 27082025 	sysconfig-Setup-Camera-Whitefader-BCAFB 
sysconfig-Setup-Camera-Whitefader-AC 	sysconfig-Setup-Camera-Iris 	sysconfig-Setup-Camera-Zoom 	Full View Matrix APM 	sysconfig-Setup-LineCam-imp0-PRNU BC 
sysconfig-Setup-LineCam-imp0-PRNU AC 	sysconfig-Setup-LineCam-imp1-PRNU BC 	sysconfig-Setup-LineCam-imp1-PRNU AC 	Full View 100% APM 	Full View 100% APM2 
BARECODE RESULT AFTER PM 				