

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Lysipack 231484 Gaëtan LIEVRE ZI de Merpins Avenue des Torulas, 16100 Merpins France 0033650887065 maintenance@lysipack.fr
--	---

Preventive reference number	PMREPORT-31_PM582_2023-12-14
Contract number / Numéro de contrat	CM2004030
Contract date:	2020/08/01 -> 2024/07/31
Machine customer name:	BOBST
Assign to:	RelR
Material:	VIDEO_IPQ_Center
SN:WA:	WA021179_ASO067320
Installation date of material:	2020/08/14

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE01.0-3
PC NAME	21179-IPQ-Center1-1
ADDITIONAL CAMERA INFO	IPQ Center
OPERATION SYSTEM	Win10Pro
MEMORY RAM	32Go
FREE SPACE ON C	50.1Gb
FREE SPACE ON D	67.4Gb
TEAMVIEWER ID	109 946 464 / v15
IP ADDRESS EXTERN FOR INTERNET	IP : 192.168.1.20 Sous réseau : 255.255.255.0 Passerelle : 192.168.1.1 DNS : 8.8.8.8 DNS Aux : 8.8.4.4
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touchmonitorcalibration	OK		Ipqchecksynchronization	OK	
Pscreenresolutiontouch		1920X1080	Ipqencoderwheelfixing	OK	
Pscreenresolutionview		1920X1080	Ipqencoderwheelstatus	OK	
Hardwareconditionscrews	OK		Ipqencoderwheelrunningonweb	OK	
Hardwareconditioncables	OK		Alarmstatusindicator	OK	
Hardwareconditionconnectors	OK		Upsbatteryexchanged	NA	
Digitalcheckfan	OK		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	OK		Installation date:		2020-08-14
Traversecamera	OK		Upscommunicationchecking	OK	
Traversecameralenscleaning	OK		Softwareupdate	NA	
Traversewscamerareplaceflashbulb	NA	A changer a la prochaine maintenance.	Version upgraded		
Traversewscameracleanwindows	OK		Softwareipqtcu		1.12
Camerachangefiltercheckfan	OK		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	OK		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	NA		Softwareipqli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	NA		Softwareworkflowcommunication	NA	
Traversewscameracheckzoomirisfocuswscboard	OK		Softwareremote	OK	
Traversewscameracalibrationzoomirisfocus	OK		Operatorinstructions	NA	
Traversebackflash	NA		Backupscreenshots	NA	
Traversebackflashflashbulb	NA		Backupimage	NA	
Linecameracleanmirror	OK		Backupsoftware	OK	
Led checking+reflector checking+dome	OK				
Linecameramechanicalcheck	OK				
Linecamerabacklightmechanicalcheckjigs	OK				
Cameramechanicalalignementtoprint	NA				

Camera white calibration

NA

Customer_comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Prevoir carte Flash bulbs.

Customer signature:

BS



Jose Calo 2023-12-14T13:05:46+01:00