

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	OREP Packaging M. Christophe Mionnet 17 route de Vauzelle 37600 Loches France +33 2 47 91 13 94 christophe.mionnet@orep-packaging.fr
--	--

Preventive reference number	PMREPORT-101_PM667_2024-07-02
Contract number / Numéro de contrat	CM2306054
Contract date:	2023/07/01 -> 2026/06/30
Machine customer name:	BOBCAT
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 660 4000 / M2032C 0.1667
SN:WA:	ASO092236_50.2390
Origin BST France order:	222347
Installation date of material:	2022/11/07

TECHNICAL DATAS

PC MODEL	OptiPlex 7090
PC NAME	TubeScan502390
ADDITIONAL CAMERA INFO	TubeScan DS 660 4000 / M2032C 0.1667
OPERATION SYSTEM	Win1dows 10 Pro / 21H1
MEMORY RAM	16 Go
FREE SPACE ON C	98.2 / 237 GB
FREE SPACE ON D	-
TEAMVIEWER ID	363 341 548 / v15
IP ADDRESS EXTERN FOR INTERNET	IP Address : 192.168.10.50 Subnet mask : 255.255.255.0 Default gateway : 192.168.10.60 Preferred DNS server : 192.168.10.202 Alternative DNs server :
ORIGINAL VERSION	7.4.30.79
UPG OR DNG VERSION DURING MAINTENANCE	8.0.27.24429

	COMMENTS		COMMENTS
Touch monitor calibration	OK	Fixation encoder	OK
Touch monitor resolution	1920X1080	Encoder wheel status	OK
View monitor resolution	2560x1440	Encoder wheel on web?	OK
Fixation screws of system?	OK	Spring(s encoder status ?	OK
Cables status ?	OK	Alarm indicator status ?	NA
Connectors cameras (well tight?)	OK		
PC's fans ?	OK		
PC's filter	NA	Installation date:	2022-11-07
Lens cleaning	OK		
Mirror cleaning	NA	Softwareworkflowcommunication	NA
Backing or RRB cleaining	OK	Check Teamviewer access	OK
Lens Focal	OK	Calibration of camera detail & 100%camera	NA
Camera alignement with printing	NA	Operators instruction ?	KO
Check web under camera	OK	Screenshots	OK
Height compensator calib	OK	ACRONIS ?	KO
Encoder offset calib	OK	Backup application	OK
Only with EV- LED calibrations	NA		
Kisspoint only with 2 cameras	NA		

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

- | | | |
|---|--------------------------------|---|
| ✓ | <input type="text" value="0"/> | ENCODER WHEEL:: 2RDHO234275 |
| ✓ | <input type="text" value="0"/> | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ✓ | <input type="text" value="0"/> | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ✓ | <input type="text" value="0"/> | ENCODER'S SPRING |
| ✓ | <input type="text" value="0"/> | BACKPLATE W/B |

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Done. System was upgradde from v8.0.10.21476 to v8.0.27.24429

Customer signature:

Name:

Date :



jeudi 4 juillet 2024 11:03:05

BST eltromat FRANCE signature:

Name:

Date :



jeudi 4 juillet 2024 11:03:34

ATTACHED PM'S FILE(S)

[Screenshot 02072024](#)

