

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	DS Smith Chateaubenard Cognac 230166 M. Florent Seigneurin ZI de chateaubernard 16102 Cognac France +33 5 45 35 49 91 florent.seigneurin@dssmith.com
--	---

Preventive reference number	PMREPORT-332_PM969_2025-09-25
Contract number / Numéro de contrat	CM1805016
Contract date:	2024/07/01 -> 2027/06/30
Machine customer name:	Cobden Chadwick
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO092237_WA0022285
Origin BST France order:	222349
Installation date of material:	2023/10/20

TECHNICAL DATAS

PC MODEL	Beg-BKA-BSTE04
PC NAME	22285iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Entreprise LTSC / 2018
MEMORY RAM	96 GB
FREE SPACE ON C	31.1 / 75.1 GB
FREE SPACE ON D	F:\ 7.19 / 7.27 TB
TEAMVIEWER ID	https://citrixcloud.dssmith.com/logon/LogonPoint/index.html
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	24/09/2025 13:30
End time PM:	24/09/2025 17:00

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✓	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	✓	4 filters under camera heads	Installation date:		2023-10-20 -> 01 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	Last version on this Base Image
Traversewscamerareplaceflashbulb	✗	Next maintenance	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓	2 filters	Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	⏸		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	⏸		Softwareremote	✓	Via citrix platform
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	✓	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	✓	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	⏸				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Preventive Maintenance Done

Customer signature:

Name: **M. Christophe Andrieu**

Date : **25/09/2025**

BST eltromat FRANCE signature:




Name: **M. Arnaud Darcel**

Date : **25/09/2025**

25-Sep-25 3:56 PM

25-Sep-25 3:55 PM

ATTACHED PM'S FILE(S)

Screenshot 25092025 	sysconfig-Setup-Camera-Whitefader-BC 	sysconfig-Setup-Camera-Whitefader-AC 	sysconfig-Setup-Camera-Iris-AC 	sysconfig-Setup-Camera-Zoom-AC 
Matrix Full View after cleaning 	sysconfig-Setup-LineCam-ipm0-PRNU-AC 	sysconfig-Setup-LineCam-ipm1-PRNU-AC 	sysconfig-Setup-LineCam-ipm2-PRNU-AC 	sysconfig-Setup-LineCam-ipm3-PRNU-AC 
Matrix Full View Jobtest 	Picture 25092025 			