

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	LithoBru (Cognac) ACU230212 M. Serge Eicheldinger Avenue des Torulas – ZI Merpins – CS 90 250 16112 Cognac France +33 5 45 81 01 16 / +33 6 47 69 62 77 serge.eicheldinger@lithobru.com
--	--

Preventive reference number	PMREPORT-334_PM971_2025-09-26
Contract number / Numéro de contrat	CM2303049
Contract date:	2023/10/01 -> 2026/09/30
Machine customer name:	Gallus 5
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 330 4K / M2089aC 0.0833
SN:WA:	ASO089809_42.2346
Origin BST France order:	222249
Installation date of material:	2022/10/12

TECHNICAL DATAS

PC MODEL	OptiPlex 7090 / Tag 5499DQ3
PC NAME	TubeScan422346
ADDITIONAL CAMERA INFO	TubeScan DS 330 4K / M2089aC 0.0833
OPERATION SYSTEM	Windows 10 Pro / v22H2
MEMORY RAM	16 GB(2x 8 3200 MHz)
FREE SPACE ON C	114 / 237 GB
FREE SPACE ON D	-
TEAMVIEWER ID	1 049 117 747 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic
ORIGINAL VERSION	7.4.55.19495
UPGRADE OR DOWNGRADE VERSION LAST INTERVENTION	7.4.63.28547 from E2160
UPG OR DNG VERSION DURING MAINTENANCE	8.0.42.39529 hotfix-11

Start time PM:	25/09/2025 08:30
End time PM:	25/09/2025 10:30

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	Cleaned
View monitor resolution		1920x1080	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✗	
PC's fans ?	✓		Date UPS's batteries exchanged ?		2022/09/01
PC's filter	⏸		Installation date:		2022-10-12 -> 03 YEAR(S)
Lens cleaning	✓	Looking up	UPS communication?	✓	Software reinstalled
Mirror cleaning	✓		Software workflow communication	⏸	
Backing or RRB cleaning	✓		Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100% camera	⏸	
Camera alignment with printing	✓		Operators instruction ?	✓	Operator : Alain
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	✓	Acronis on v8.0.42.39529 hotfix-11
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓ ENCODER WHEEL:: 2RDHO234275
- ✓ LED Board equipped V40 L=140mm: 1ELLT256485
- ✓ LED Board equipped V40 L=160mm: 1ELLT256486
- ✓ ENCODER'S SPRING
- ✓ BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Done
-Upgrade to version 8 + training
- UPS software reinstalled : Need to replace Batteries on next PM.

Customer signature:

Name:

Date :

26-Sep-25 11:04 AM

BST eltromat FRANCE signature:

Name:

Date :

26-Sep-25 11:04 AM

ATTACHED PM'S FILE(S)

Picture 26092025	Screenshot 26092025
	