

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Wipak 231056 M. Eric Ghesquier Drèce des Bois 59166 Bousbecque France +33 6 07 01 64 56 eric.ghesquier@wipak.com
--	---

Preventive reference number	PMREPORT-275_PM897_2025-06-01
Contract number / Numéro de contrat	CM2005031
Contract date:	2023/10/01 -> 2026/09/30
Machine customer name:	Grafomac
Assign to:	SalG
Material:	VIDEO_IPQ_Center
Type:	IPQ Center
SN:WA:	ASO067953 _ WA0021190
Installation date of material:	2020/09/23

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE01.0-3
PC NAME	21190iPQ-Center1-1
ADDITIONAL CAMERA INFO	IPQ Center
OPERATION SYSTEM	Win10Pro
MEMORY RAM	32Go
FREE SPACE ON C	51.8Go/E:48.7Go
FREE SPACE ON D	97.1Go/F:1.74
TEAMVIEWER ID	212 661 068 / v12
IP ADDRESS EXTERN FOR INTERNET	192.168.1.59
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	01/06/2025 11:25
End time PM:	

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	
Digitalcheckfan	⏸		Upsdatebatteryexchanged		2024/12/18
Digitalreplacefilter	⏸		Installation date:		2020-09-23
Traversecamera	✓		Upscommunicationchecking	✗	UPS software update has been done; communication OK now
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✓	8 new bulbs for camera	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓	cleaning	Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	✓	5 new bulbs for vanish flash	Softwareipqli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	✓		Softwareworkflowcommunication	✗	no computer for report generator
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	⏸	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	✓	
Led checking+reflector checking+dome	✓	but the backlight has ink on it creating some light lines			
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	⏸				
Cameraalignmenttoprint	✓				
Camerawhitecalibration	⏸	white is ok			

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name: **Saussol Benoit**

Date : **12/06/2025**

BST eltromat FRANCE signature:

Name: **Salaun Gael**

Date : **12/06/2025**


12/06/2025 14:54


12/06/2025 15:20