

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CEE Robert Schisler 231405 M. Julien Berthet 156 avenue Emile Zola 79104 Thouars France +33 5 49 68 13 77 julien.berthet@ceeschisler.fr
--	--

Preventive reference number	PMREPORT-294_PM921_2025-06-19
Contract number / Numéro de contrat	CM2303048
Contract date:	2023/04/01 -> 2026/03/31
Machine customer name:	M226
Assign to:	RelR
Material:	VIDEO_IPQ_View
Type:	webvideo_star 1000
SN:WA:	WA0018397
Installation date of material:	2018/09/15

TECHNICAL DATAS

PC MODEL	Optiplex 3010
PC NAME	12345WVSTAR1-1
ADDITIONAL CAMERA INFO	webvideo_star 1000
OPERATION SYSTEM	Windows7pRO
MEMORY RAM	4Gb
FREE SPACE ON C	16.6Go/E:79.8Go
FREE SPACE ON D	11.2Go /F:99.3Go
TEAMVIEWER ID	368 973 737
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	42
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	18/06/2025 14:58
End time PM:	18/06/2025 17:00

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1024X768	Ipqencoderwheelfixing	⏸	
Pcscreenresolutionview		1920X1080	Ipqencoderwheelstatus	⏸	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	⏸	
Hardwareconditioncables	✓		Alarmstatusindicator	⏸	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	Pas de date de change a surveiller
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2018-09-15 -> 06 YEAR(S)
Traversecamera	✓	Alimentation n'est pas d'origine.	Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✓	1 Condensateur en haut HS du coup seulement 7 flash sur 8 fonctionne	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.8.2
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.4.13
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		1.4.2
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	⏸	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	⏸	
Traversewscameracalibrationzoomirisfocus	⏸		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	⏸	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
			Backupsoftware	✓	

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :


19/06/2025 14:26


19/06/2025 14:17

ATTACHED PM'S FILE(S)

[Alimentation pas d'origine](#)

