

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Atlantique Packaging Cotentin - CPC Cotentin 231515 M. Cédric Fautrat Chemin de la Canurie 50250 La Haye-du-Puits France +33 2 33 07 33 11 / +33 7 80 61 36 91 maintenance-cotentin@atlantiquepackaging.com
--	--

Preventive reference number	PMREPORT-140_PM727_2024-10-18
Contract number / Numéro de contrat	CM1912025
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	Rotomec
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO059410_WA0020827
Origin BST France order:	192318
Installation date of material:	2018/12/05

TECHNICAL DATAS

PC MODEL	IPC-BKA-BSTE02
PC NAME	20827iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise 2016 LTSC
MEMORY RAM	48 GB
FREE SPACE ON C	50.7 / 75.1 GB
FREE SPACE ON D	F:\ 1.75 / 1.81 TB
TEAMVIEWER ID	1 296 881 336 / v15
IP ADDRESS EXTERN FOR INTERNET	IP address : 10.50.21.13 Subnet mask : 255.255.255.0 Default gateway : 10.50.21.1 Preferred DNS server : 10.50.21.1 Alternate DNS server :
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✗	Battery Down. Need new UPS asap
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2018-12-05 -> 05 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	✗	
Traversewscamerareplaceflashbulb	⏸	Replaced 20240326	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqjli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	✓	
Traversebackflash	✓	MUst be replaced newt visit	Backupscreenshots	✓	
Traversebackflashflashbulb	✗		Backupimage	✗	
Linecameracleanmirror	✓		Backupsoftware	✗	ipq-center_bak_2024_10_16_16_47_30
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)


(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance sur système iPQ Center

Customer signature:

Name:

Date :



vendredi 18 octobre 2024 11:36:40

BST eltromat FRANCE signature:





Name:

Date :



vendredi 18 octobre 2024 11:31:09

ATTACHED PM'S FILE(S)

sysconfig-Setup-Camera-Whitefader-BC 	sysconfig-Setup-Camera-Whitefader-AC 	sysconfig-Setup-Camera-Iris 	sysconfig-Setup-Camera-Zoom 	sysconfig-Setup-LineCam-ipm0-BAlign 
sysconfig-Setup-LineCam-ipm0-AAAlign 	sysconfig-Setup-LineCam-ipm1-BAlign 	sysconfig-Setup-LineCam-ipm1-AAAlign 	sysconfig-Setup-LineCam-ipm0-BPRNU 	sysconfig-Setup-LineCam-ipm0-APRNU-FPN 
sysconfig-Setup-LineCam-ipm1-BPRNU 	sysconfig-Setup-LineCam-ipm1-APRNU-FPN 	Application - Full View after PRNU-FPN 	Screenshot 16102024 	