

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	DS Smith Sud-Est ACU231662 M. Jérôme Pipet 112 Impasse du Pré de la Barre 38440 Saint Jean de Bournay France +33 4 74 59 7 4 32 jerome.pipet@dssmith.com
--	---

Preventive reference number	PMREPORT-295_PM935_2025-06-24
Contract number / Numéro de contrat	Please fill system information
Contract date:	
Machine customer name:	iPQ Center
Assign to:	SalG
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO103327_WA0022918
Installation date of material:	2024/04/16

TECHNICAL DATAS

PC MODEL	Beg-BKA-BSTE04
PC NAME	22918-iPQ-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Entreprise LTSC / 2018
MEMORY RAM	96 GB
FREE SPACE ON C	39.2.6 / 75.0 GB
FREE SPACE ON D	F:\ 7.23 / 7.25 TB
TEAMVIEWER ID	https://citrixcloud.dssmith.com/login/LogonPoint/index.html
IP ADDRESS EXTERN FOR INTERNET	IP address : 192.168.1.20 Subnet mask : 255.255.255.0 Default gateway : Preferred DNS server : Alternate DNS server :
ORIGINAL VERSION	3.2.2
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	23/06/2025 13:30
End time PM:	23/06/2025 17:30

COMMENTS			COMMENTS		
Touchmonitorcalibration	✓		Ipqchecksynchronization	⏸	
Pcscreenresolutiontouch			Ipqencoderwheelfixing	✓	
Pcscreenresolutionview			Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	
Digitalcheckfan	⏸		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	⏸		Installation date:		2024-04-16 -> 01 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	⏸		Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.14.0
Camerachangefiltercheckfan	✓	cleaning	Softwareipqwsc		1.9.7
Traversewscamerashadowreducingbackplate	⏸		Softwareipqpps		NA
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqjli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	⏸	no teamviewer
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	⏸	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	⏸				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	⏸				

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :



24/06/2025 16:48



24/06/2025 16:48