

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	SBE Societe bretonne étiquette ACU531001 M. Nicolas Robert 17 Rue Théodore Botrel 35550 Pipriac France + 33 2 99 34 37 49 atelier.flexo@sbe-etiquettes.fr
--	--

Preventive reference number	PMREPORT-148_PM720_2024-11-07
Contract number / Numéro de contrat	CM2310056
Contract date:	2023/10/01 -> 2026/09/30
Machine customer name:	MPS 8
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 330 4000 / M2032aC 0.0833
SN:WA:	ASO091667_50.2397
Origin BST France order:	222324
Installation date of material:	2022/12/02

TECHNICAL DATAS

PC MODEL	OptiPlex 7090
PC NAME	TubeScanPC
ADDITIONAL CAMERA INFO	TubeScan DS 330 4000 / M2032aC 0.0833
OPERATION SYSTEM	Windows 10 Professionnel / v21H1
MEMORY RAM	16 GB
FREE SPACE ON C	111 / 237 GB
FREE SPACE ON D	-
TEAMVIEWER ID	429 903 817 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic
ORIGINAL VERSION	7.4.55.19495
UPG OR DNG VERSION DURING MAINTENANCE	7.4.64.29287

		COMMENTS			COMMENTS
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	Replaced (Offre_241011-0209)
View monitor resolution		1920x1080	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✗	
PC's fans ?	✓		Date UPS's batteries exchanged ?		2022/02/01
PC's filter	⏸		Installation date:		2022-12-02 -> 02 YEAR(S)
Lens cleaning	✓		UPS communication?	✓	
Mirror cleaning	⏸		Softwareworkflowcommunication	⏸	
Backing or RRB cleaning	✓	Scratched : Need to be replaced for transparent material.	Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100%camera	✓	
Camera alignement with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	✓	Overlapping Adjusted			

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

	ENCODER WHEEL:: 2RDHO234275
	LED Board equipped V40 L=140mm: 1ELLT256485
	LED Board equipped V40 L=160mm: 1ELLT256486
	ENCODER'S SPRING
✓ 1	BACKPLATE W/B

-  : Checked, nothing to report / Vérifié, RAS
 : Not OK, checked comment / Pas OK, vérifiez commentaires
 : Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Maintenance preventive sur press MPS. Mise a jour logiciel. Batteries onduleur HS.
Overlapping camera OK

Customer signature:

Name:

Date :


jeudi 7 novembre 2024 17:31:08

BST eltromat FRANCE signature:

Name:

Date :


jeudi 7 novembre 2024 17:30:38

ATTACHED PM'S FILE(S)

Picture 07112024	Screenshot 07112024
	