

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Socoplan (Arcade Beauty) ACU230223 M. Franck Bourdon 12 All. De Dissé 79600 Airvault France +33 6 07 48 31 95 / +33 5 49 64 95 01 f.bourdon@arcadebeauty.com
--	---

Preventive reference number	PMREPORT-103_PM668_2024-07-04
Contract number / Numéro de contrat	CM2112043 R2
Contract date:	2024/01/01 -> 2026/12/31
Machine customer name:	DCM 3
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO076651_WA21547
Origin BST France order:	212174
Installation date of material:	2021/08/26

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE03.0-2
PC NAME	21547IPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise LTSC - v1809
MEMORY RAM	64 GB
FREE SPACE ON C	44.3 / 75.1 GB
FREE SPACE ON D	F:\ 7.15 / 7.27 TB
TEAMVIEWER ID	280 278 141 / v15
IP ADDRESS EXTERN FOR INTERNET	IP address : 172.20.11.50 Subnet mask : 255.255.255.0 Default gateway : 172.20.11.254 Preferred DNS server : 172.20.20.10 Alternate DNS server : 10.217.3.10
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touchmonitorcalibration	OK		Ipqchecksynchronization	OK	
Pcscreenresolutiontouch		1920X1080	Ipqencoderwheelfixing	OK	
Pcscreenresolutionview		1920X1080	Ipqencoderwheelstatus	OK	
Hardwareconditionscrews	OK		Ipqencoderwheelrunningonweb	OK	
Hardwareconditioncables	OK		Alarmstatusindicator	OK	
Hardwareconditionconnectors	OK		Upsbatteryexchanged	OK	
Digitalcheckfan	OK		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	OK		Installation date:		2021-08-26 -> 02 YEAR(S)
Traversecamera	OK		Upscommunicationchecking	OK	
Traversecameralenscleaning	OK		Softwareupdate	KO	
Traversewscamerareplaceflashbulb	KO		Version upgraded		
Traversewscameracleanwindows	OK		Softwareipqtcu		1.12
Camerachangefiltercheckfan	OK		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	OK		Softwareipppps		2.2
Traversewscameracheckflashbulblackerflash	NA		Softwareipqli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	NA		Softwareworkflowcommunication	OK	
Traversewscameracheckzoomirisfocuswscboard	OK		Softwareremote	OK	
Traversewscameracalibrationzoomirisfocus	OK		Operatorinstructions	KO	
Traversebackflash	NA		Backupscreenshots	OK	
Traversebackflashflashbulb	NA		Backupimage	OK	
Linecameracleanmirror	OK		Backupsoftware	OK	ipq-center_bak_2024_07_04_16_44_51
Led checking+reflector checking+dome	OK				
Linecameramechanicalcheck	OK				
Linecamerabacklightmechanicalcheckjigs	OK				
Camera mechanicalalignementtoprint	OK				
Camera whitecalibration	OK				

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :






vendredi 5 juillet 2024 11:54:35



vendredi 5 juillet 2024 11:54:57

ATTACHED PM'S FILE(S)

sysconfig-Setup-Camera-Whitefader 	sysconfig-Setup-Camera-Iris 	sysconfig-Setup-Camera-Zoom 	sysconfig-Setup-LineCam-ipm0-Alignment-FOV 	sysconfig-Setup-LineCam-ipm0-PRNU 
Screenshot 04072024 				