

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Atlantique Packaging Cotentin - CPC Cotentin 231515 M. Cédric Fautrat Chemin de la Canurie 50250 La Haye-du-Puits France +33 2 33 07 33 11 / +33 7 80 61 36 91 maintenance-cotentin@atlantiquepackaging.com
--	--

Preventive reference number	PMREPORT-139_PM723_2024-10-17
Contract number / Numéro de contrat	CM1912025
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	BOBST
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO045079_WA0020214
Installation date of material:	2018/12/15

TECHNICAL DATAS

PC MODEL	PC-BKA-BSTE02
PC NAME	20214iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise 2016 LTSC
MEMORY RAM	48 GB
FREE SPACE ON C	50.7 / 75.1 GB
FREE SPACE ON D	F:\ 1.75 / 1.81 TB
TEAMVIEWER ID	1 035 997 951 / v15
IP ADDRESS EXTERN FOR INTERNET	IP address : 10.50.21.14 Subnet mask : 255.255.255.0 Default gateway : 10.50.21.1 Preferred DNS server : 10.50.21.1 Alternate DNS server :
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080 - Duplicate desktop on 1 and 2	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2018-12-15
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✗	Replaced 20240326	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackflash	⏸		Softwareipqjli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓	Calibrated	Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	ipq-center_bak_2024_10_17_11_42_37
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓	Calibrated			
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance sur système iPQ Center.

Customer signature:


Name:

Date :

BST eltromat FRANCE signature:





Name:

Date :


vendredi 18 octobre 2024 11:37:18


vendredi 18 octobre 2024 11:30:44

ATTACHED PM'S FILE(S)

sysconfig-Setup-Camera-Whitfader-BC 	sysconfig-Setup-Camera-Whitfader-AC 	sysconfig-Setup-Camera-Iris 	sysconfig-Setup-Camera-Zoom 	sysconfig-Setup-LineCam-ipm0-AAAlign 
sysconfig-Setup-LineCam-ipm1-AAAlign 	sysconfig-Setup-LineCam-ipm0-BPRNU 	sysconfig-Setup-LineCam-ipm0-APRNU-FPN 	sysconfig-Setup-LineCam-ipm1-BPRNU 	sysconfig-Setup-LineCam-ipm1-APRNU-FPN 
Application - Full View after PRNU-FPN 	Screenshot 17102024 			