

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Adhex Technologies 231128 M. Franck Leborne 44 Rue de Longvic 21300 Chenôve France +33 6 21 31 68 54 f.leborne@adhex.com
--	---

Preventive reference number	PMREPORT-313_PM951_2025-07-22
Contract number / Numéro de contrat	CM1911023
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	BOB.20
Assign to:	RelR
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 250 4K
SN:WA:	ASO111765_50.3211
Origin BST France order:	242396
Installation date of material:	2025/05/05

TECHNICAL DATAS

PC MODEL	Optiplex 3090
PC NAME	TubeScan503211
ADDITIONAL CAMERA INFO	TubeScan DS 250 4K
OPERATION SYSTEM	Windows 11 Pro version:23H2
MEMORY RAM	32 GB
FREE SPACE ON C	142 Go
FREE SPACE ON D	
TEAMVIEWER ID	1 420 899 370
IP ADDRESS EXTERN FOR INTERNET	192.168.1.112 255.255.255.0 192.168.1.253 DNS 10.75.20.207
ORIGINAL VERSION	8.0.39.32918
UPGRADE OR DOWNGRADE VERSION LAST INTERVENTION	8.0.42 from E2535
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	22/07/2025 08:35
End time PM:	22/07/2025 09:30

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1920X1080	Encoder wheel status	✓	
View monitor resolution		1920X1080	Encoder wheel on web?	✓	Too many false defects when on web so encoder on roller.
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	Only I/O
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	⏸	
PC's fans ?	✓		Date UPS's batteries exchanged ?		<u>OLD UPS APC NEW UPS EATON</u> recommand to exchange every 5 years.
PC's filter	⏸		Installation date:		2025-05-05 -> 00 YEAR(S)
Lens cleaning	✓		UPS communication?	✓	
Mirror cleaning	✓		Softwareworkflowcommunication	✓	Qlink
Backing or RRB cleaining	✓		Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100%camera	⏸	
Camera alignement with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

- ✅: Checked, nothing to report / Vérifié, RAS
❌: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :


23/07/2025 10:39

BST eltromat FRANCE signature:

Name:

Date :


23/07/2025 10:39