

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Lysipack 231484 Gaëtan LIEVRE ZI de Merpins Avenue des Torulas, 16100 Merpins France 0033650887065 maintenance@lysipack.fr
--	---

Preventive reference number	PMREPORT-237_PM843_2025-03-14
Contract number / Numéro de contrat	CM2004030
Contract date:	2020/08/01 -> 2024/07/31
Machine customer name:	BOBST
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	WA021179_ASO067320
Origin BST France order:	202161
Installation date of material:	2020/08/14

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE01.0-3
PC NAME	21179iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise 2016 LTSC
MEMORY RAM	32 GB
FREE SPACE ON C	51.1 / 75.7 GB
FREE SPACE ON D	F:\ 1.74 / 1.81 TB
TEAMVIEWER ID	109 946 464 / v15
IP ADDRESS EXTERN FOR INTERNET	IP : 192.168.1.21 Sous réseau : 255.255.0.0 Passerelle : 192.168.1.1 DNS : 8.8.8.8 DNS Aux : 8.8.4.4
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	14/03/2025 15:06
End time PM:	

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920X1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920X1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✓	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2020-08-14 -> 04 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	⏸		Version upgraded		
Traversewscameracleanwindows	⏸		Softwareipqtcu		1.12
Camerachangefiltercheckfan	⏸		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	⏸		Operatorinstructions	✓	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	
Led checking+reflector checking+dome	✓	Reflecteur utilisé			
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	⏸				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name: **Josø Calo**
 Date :

BST eltromat FRANCE signature:

Name: **Vivien Coutellier**
 Date :


 14/03/2025 15:18


 14/03/2025 15:18