

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Amcor (Sarrebourg) 231254 M. Thierry Richard 48 rue de Sarreguemines 57400 Sarrebourg France +33 3 87 24 53 43 thierry.richard@amcor.com
--	---

Preventive reference number	PMREPORT-247_PM857_2025-03-28
Contract number / Numéro de contrat	Please fill system information
Contract date:	
Machine customer name:	327
Assign to:	RelR
Material:	VIDEO_Tubescan_DS
Type:	TubeScan XL 1400
SN:WA:	ASO088520_42.2271
Installation date of material:	2023/01/09

TECHNICAL DATAS

PC MODEL	Optiplex 7080
PC NAME	Tubescan422271
ADDITIONAL CAMERA INFO	TubeScan XL 1400
OPERATION SYSTEM	Win10Pro
MEMORY RAM	32Go
FREE SPACE ON C	126Gb
FREE SPACE ON D	
TEAMVIEWER ID	733048226
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.35.87
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	28/03/2025 08:30
End time PM:	28/03/2025 11:00

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024X768	Encoder wheel status	✗	Roue a changer usure anormal
View monitor resolution		2560X1440	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	⏸	
PC's fans ?	✓		Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommend to exchange every 5 years.
PC's filter	⏸		Installation date:		2023-01-09 -> 02 YEAR(S)
Lens cleaning	✓		UPS communication?	✓	
Mirror cleaning	✓		Softwareworkflowcommunication	✓	
Backing or RRB cleaning	✓		Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100%camera	⏸	
Camera alignment with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	⏸	
Height compensator calib	✓		ACRONIS ?	✓	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	✓				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

1	ENCODER WHEEL:: 2RDHO234275
	LED Board equipped V40 L=140mm: 1ELLT256485
	LED Board equipped V40 L=160mm: 1ELLT256486
	ENCODER'S SPRING
	BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

UPS 60%, prévoir le changement. Tubescan dØcroche a 350m/mn+, cause probable roue codeuse a verifier apres changement.

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :


28/03/2025 14:58


28/03/2025 11:51