

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CONSTANTIA Jeanne d'Arc SAS 231032 M. François Bodhuin B.P. 51 52300 Vecqueville France +33 3 25 94 77 75 / +33 6 74 57 25 31 francois.bodhuin@cflex.com
--	---

Preventive reference number	PMREPORT-131_PM707_2024-09-23
Contract number / Numéro de contrat	CM2104038
Contract date:	2022/01/01 -> 2024/12/31
Machine customer name:	Tigre 2
Assign to:	RelR
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS XL 1400 / M2032C-0.24
SN:WA:	ASO072409_42.1661
Installation date of material:	2021/04/01

TECHNICAL DATAS

PC MODEL	OptiPlex 7080
PC NAME	TubeScan421661
ADDITIONAL CAMERA INFO	TubeScan DS XL 1400 / M2032C-0.24
OPERATION SYSTEM	Windows 10 Pro / 2019
MEMORY RAM	16 GB
FREE SPACE ON C	64.0 / 237 GB
FREE SPACE ON D	Z:\ Rapports BST Tigre2
TEAMVIEWER ID	833 553 740 / v15
IP ADDRESS EXTERN FOR INTERNET	IP address : 10.140.164.82 Subnet mask : 255.255.255.0 Default gateway : 10.140.164.254 Preferred DNS server : 10.140.173.161 Alternate DNS server :
ORIGINAL VERSION	7.4.55.19495
UPG OR DNG VERSION DURING MAINTENANCE	7.4.64.29287

		COMMENTS			COMMENTS
Touch monitor calibration	OK		Fixation encoder	OK	
Touch monitor resolution		1024x768	Encoder wheel status	OK	
View monitor resolution		2560X1440	Encoder wheel on web?	OK	
Fixation screws of system?	OK		Spring(s) encoder status ?	OK	
Cables status ?	OK		Alarm indicator status ?	OK	
Connectors cameras (well tight?)	OK	Parasites sur ecran view en haut et dans le bas	UPS battery exchanged ?	OK	
PC's fans ?	OK		Date UPS's batteries exchanged ?		2024/09/23
PC's filter	NA		Installation date:		2021-04-01 -> 00 YEAR(S)
Lens cleaning	OK		UPS communication?	OK	
Mirror cleaning	NA		Software workflow communication	NA	
Backing or RRB cleaning	NA		Check Teamviewer access	OK	connection is not possible unless using a phone or network box or via VNC
Lens Focal	NA		Calibration of camera detail & 100% camera	NA	
Camera alignment with printing	OK		Operators instruction ?	NA	
Check web under camera	OK		Screenshots	OK	
Height compensator calib	OK		ACRONIS ?	NA	
Encoder offset calib	OK		Backup application	OK	
Only with EV- LED calibrations	NA				
Kisspoint only with 2 cameras	OK				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

	ENCODER WHEEL:: 2RDHO234275
	LED Board equipped V40 L=140mm: 1ELLT256485
	LED Board equipped V40 L=160mm: 1ELLT256486
	ENCODER'S SPRING
	BACKPLATE W/B

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Onduleur toujours pas arriver.

Customer signature:

Name: Francois Bodhuin

Date : 25/09/2024

BST eltromat FRANCE signature:

Name: Richard Relin

Date : 25/09/2024

25/09/2024 12:09

ATTACHED PM'S FILE(S)

[systeme allumer](#)

