

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	DS Smith Velin ACU231586 Olivier DIDIER ZI de la plaine 88510 ELOYES France 06 49 82 45 67 olivier.didier@dssmith.com
--	--

Preventive reference number	PMREPORT-225_PM812_2025-02-19
Contract number / Numéro de contrat	CM2501071
Contract date:	2025/02/01 -> 2028/01/31
Machine customer name:	Cobden & Chadwick
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO100401_WA0022760
Origin BST France order:	232276
Installation date of material:	2024/01/29

TECHNICAL DATAS

PC MODEL	BKA-BSTE04
PC NAME	22760-IPQ-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise LTSC - v1809
MEMORY RAM	96 GB
FREE SPACE ON C	38.6 GB / 75.0 GB
FREE SPACE ON D	F:\ 7.25 TB / 7.27 TB
TEAMVIEWER ID	https://citrixcloud.dssmith.com/logon/LogonPoint/index.html
IP ADDRESS EXTERN FOR INTERNET	192.168.1.23 255.255.255.0
ORIGINAL VERSION	3.1
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	17/02/2025 13:30
End time PM:	17/02/2025 17:30

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	⏸	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2024-01-29 -> 01 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✓		Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		.
Traversewscamerashadowreducingbackplate	⏸		Softwareipqpps		no
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		.
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	✓	
Traversebackflash	✓		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name: **Leclere Florent**


Date :

BST eltromat FRANCE signature:

Name: **Coutellier Vivien**

Date :


20/02/2025 17:25


21/02/2025 19:47