

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CONSTANTIA Jeanne d'Arc SAS 231032 M. François Bodhuin B.P. 51 52300 Vecqueville France +33 3 25 94 77 75 / +33 6 74 57 25 31 francois.bodhuin@cfllex.com
--	--

Preventive reference number	PMREPORT-81_PM641_2024-05-03
Contract number / Numéro de contrat	CM2104038
Contract date:	2022/01/01 -> 2024/12/31
Machine customer name:	Tigre 2
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS XL 1400 / M2032C-0.24
SN:WA:	ASO072409_42.1661
Installation date of material:	2021/04/01

TECHNICAL DATAS

PC MODEL	OptiPlex 7080
PC NAME	TubeScan421661
ADDITIONAL CAMERA INFO	TubeScan DS XL 1400 / M2032C-0.24
OPERATION SYSTEM	Windows 10 Pro / 2019
MEMORY RAM	16 GB
FREE SPACE ON C	64.0 / 237 GB
FREE SPACE ON D	Z:\ Rapports BST Tigre2
TEAMVIEWER ID	833 553 740 / v15
IP ADDRESS EXTERN FOR INTERNET	IP address : 10.140.164.82 Subnet mask : 255.255.255.0 Default gateway : 10.140.164.254 Preferred DNS server : 10.140.173.161 Alternate DNS server :
ORIGINAL VERSION	7.4.55.19495
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touch monitor calibration	OK		Fixation encoder	OK	
Touch monitor resolution		1024x768	Encoder wheel status	OK	
View monitor resolution			Encoder wheel on web?	OK	
Fixation screws of system?	OK		Spring(s) encoder status ?	OK	
Cables status ?	OK		Alarm indicator status ?	NA	
Connectors cameras (well tight?)	OK		UPS battery exchanged ?	KO	
PC's fans ?	OK	On Cabinet	Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommand to exchange every 5 years.
PC's filter	NA		Installation date:		2021-04-01 -> 03 YEAR(S)
Lens cleaning	OK		UPS communication?	KO	
Mirror cleaning	NA	Direct View	Softwareworkflowcommunication	NA	
Backing or RRB cleaining	OK		Check Teamviewer access	OK	
Lens Focal	OK		Calibration of camera detail & 100%camera	NA	
Camera alignement with printing	OK		Operators instruction ?	OK	
Check web under camera	OK		Screenshots	KO	
Height compensator calib	OK		ACRONIS ?	KO	
Encoder offset calib	OK		Backup application	OK	
Only with EV- LED calibrations	NA				
Kisspoint only with 2 cameras	OK				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |


Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :


Franck Gavier 2024-05-03T11:55:13+02:00

BST eltromat FRANCE signature:

Name:

Date :


Arnaud Darcel 2024-05-03T11:55:33+02:00

ATTACHED PM'S FILE(S)

Erreur FF006645	Erreur FF006992	Erreur FF006994	Win-System	Win-HDD
				
Win-Network				
				