

On Customer Site

Visit Report

Reference :

Commande BSTe France : CM1911024		Call / PM number : PM293	
Customer :	MCC (Sautron)	System :	IPQ CENTER WV
Customer Contact :	M. Wiliam Breit	ASO / WA :	WA18922
Customer Order number :		Machine Nickname :	S7/DCM7

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☒	Under Contract	☒	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	08 / 02 / 2022		/ /	/ /	/ /	/ /
Travel To	0					
Start Time	12h00					
Lunch Time	0					
End Time	14h00					
Travel From	0.5					

Details	Maintenance , Nettoyage des lens et miroirs et backup du système .Changement des _ bulbs.
---------	---

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Customer name and place : [MCC / Zi de Tournebride, R.D. 65 F, 44880 Sautron](#)

Contact person at customer / Title : [M. William Breit \(Responsable de production\)](#)

Customer Mail & Mobile/Landline : William.breit@mcclabel.com / +33 2 28 07 24 00

System Type : [iPQ WV](#)

ASO/WA : [WA18922](#)

Machine Manufacturer/Model/Nickname : [S7/DCM 7](#)

Date : [08/02/2022](#)

Name : [Relin Richard](#)

Comments :

Signatures :



Richard Relin 2022-02-08T17:29:34+01:00



Laurent Fleury 2022-02-08T16:09:43+01:00

BST eltromat FSE

Customer

On Customer Site

Prior to a Preventive Maintenance :

Check for system affecting modification reports and software releases.

Check for iPQ-Spectral sensor replace date.

Check with customer about problems and demands.

OK/NOK/NA

1. Replace filters of cabinets, check fan function.

☒ ☐ ☐

2. Visual check of system basic hardware condition :

OK/NOK/NA

- Check if all screws are in position and tightened.
- Check cables for damages and correct fit in cable trunks.
- Check if all connectors are tightened.

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

3. Check image quality of screens with test pattern :

OK/NOK/NA

- Load test pattern from screen supplier on computer and display on all screens.
- Check for color quality, pixel defects, contrast, brightness.
- Recalibrate touch screen if necessary.

☐ ☒ ☐

☒ ☐ ☐

☒ ☐ ☐

4. Traverse and WSC-Camera according to separate instruction :

OK/NOK/NA

- Replace flash bulbs for main flash.
- Clean glasses in front of main flash.
- Change filters, check fan function.
- Clean lens from dust.
- Clean shadow reducing backplate.
- Check flash bulb in lacquer (Cold Seal) flash.
- Clean half mirrored glass in lacquer flash.
- Check ZIF function with buttons on WSC Control Board.
- Visual check and cleaning of traverse bars.

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

☐ ☐ ☒

☐ ☐ ☒

☒ ☐ ☐

☒ ☐ ☐

On Customer Site

5. Check power flash or homogeneous BackPlate :

OK/NOK/NA

- Check function of flash bulbs according to instruction.
- Clean surface of white plate.
- Visual check and cleaning of traverse bars.

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

6. Alarm status indicator :

OK/NOK/NA

- Check function of light bulbs in green, yellow and red.
- Check function of acoustic alarm.

☒ ☐ ☐

☒ ☐ ☐

7. Verify the web way in front of line cameras and under measurement wheel :

OK/NOK/NA

- There must be no waves on the web.
- The rollers must be smooth, not (max. slightly) spiraled. (ipQ-Check, sis, icm, bc).
- The guide rollers must rotate with the web speed.
- The measuring wheel must be mounted on a roller wrapped $\geq 90^\circ$ material.
- The line camera must be mounted according to project drawing.
- Web guiding unit in machine must be in operation.

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

- **Check measurement wheel :**
mechanical drawing.

Mounted according to latest

☒ ☐ ☐

- Pressure according to ipQ-Check maintenance manual. (10-15N)
- No dirt or damages on rubber surface.
- Smooth running.
- Running on the web.
- Not too far from line camera unit (≤ 1 meter).
- Rollers not or only slightly spiraled.

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

☒ ☐ ☐

OK/NOK/NA

On Customer Site

8. Exchange the UPS battery according to iPQ-Check maintenance.
☐☐☒

- Model : **EATON 3S 700**

Date : **2017**

9. Check for useful software update with release letter : (*)

OK/NOK/NA

- Update to latest released software version IF system is affected from bug fixes and/or new functions and features.

☐☒☐

- Check if an update of communication Workflow components is also necessary.

☐☐☒
10. Check function and performance of the system :

OK/NOK/NA

- Performance of 100% print defect detection.

☐☒☐

- System performance at splice situations.

☐☒☐

- System performance after "out of print" situations.

☐☒☐

- System performance close to max. iPQ check system speed.

☐☐☒

- Check function/performance of additional software options like barcode, color Monitoring, Smartregister, etc.

☐☐☒

- Check remote service function with BST eltromat RS. (**)

☒☐☐

- Teamviewer Version check and upgrade (v12) :

☒☐☐

- Check availability of system in customer network for snapshot gallery, pdf-upload And WorkFlow applications.

☐☐☒
11. Give an instruction and production guiding for system operators.

OK/NOK/NA

- Explain new functions from software upgrade

☐☒☐

- Proceed a practice training at machine about all basic functions.

☐☒☐

- Explain special functions more detailed on operators request.

☐☒☐

- Guide the production and watch how operators work with the system to give hints for a better operation.

☐☒☐

On Customer Site

12. Backup for customer :

OK/NOK/NA

- *Preconditions : above points are checked and okay* ☒ ☐ ☐
- Backup HardDisk or Image-PC exist from current Base Image -PC. ☒ ☐ ☐
- If NOK on previous point, make a new Image-PC or Backup HDD. ☒ ☐ ☐
- Write date and WA/ASO number on Backup HardDisk or Image-PC file name and give a copy to the customer. ☐ ☒ ☐

OK/NOK/NA

16. Make a backup for our own service purpose and put this on our server. (*)**☒ ☐ ☐

On Customer Site

Technical datas

Main Power 230V Input : [234V](#)

Computer name : [19944IPQ](#)

Computer description : [iPQ-Center, WA20820](#)

Total Physical Memory : [16 GB](#)

Free Space in C Drive (System) : [29.4 GB](#)

Free Space in D Drive (Data) : [99.4 GB](#)

Free Space in E Drive (Log) : [99.8 GB](#)

Free Space in F Drive (Protocol) : [206 GB](#)

OS : [Windows](#)

Screen Resolution 1 : [1280X1024](#)

Screen Resolution 2 : [1280X1024](#)

Screen Resolution 3 :

Camera Type : [ALPIXA](#)

Computer Model / Image : [OPTIPLEX](#)

(*)	Global Version :	Current : 1.1.1	New :
	TCU.x :	Current : 1.8.5	New :
	WSX_3xx/WSC_4xx :	Current : 1.3	New :
	PPS.3 :	Current :	New :
	ILI-CTRL :	Current :	New :

(**) **Remote Maintenance (Teamviewer)**

IP address : [DHCP](#)

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

On Customer Site

Remote Access (Snapshot gallery, pdf upload, WF applications)

IP address :

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID : 987 891 521 / v12

OK/NOK/NA

- | | | | | |
|-------|---|-------------------------------------|-------------------------------------|--------------------------|
| (***) | - Dcf and pdfx folder | ☐ | ☒ | ☐ |
| | - Windows Credentials | ☐ | ☒ | ☐ |
| | - iPQ-xxxxxx_bak_date_time.zip file generated from sysconfig.py | ☒ | ☐ | ☐ |
| | - MmxlpmMap file in mmx folder for Check systems (Overlapping) | ☒ | ☐ | ☐ |
| | - Screenshot from Application settings | ☒ | ☐ | ☐ |
| | - Screenshot from visconfig.py (Mmx + Srb + Image) | ☒ | ☐ | ☐ |

Parts replaced during Preventive Maintenance :

1 - 8 Bulbs 3 -

2 - 4 -

Parts suggested to replace during the next Maintenance :

1 - UPS

2 -

Part need to be replaced as soon as possible :

1 - 4 -

2- 5-

On Customer Site

Notes
