

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Livcer M. Charles de Livonnière 593 avenue Blaise Pascal - Lotissement Anaconda 2 77550 Moissy Cramayel France charles.livonniere@livcer.com
--	---

Preventive reference number	PMREPORT-159_PM750_2024-11-27
Contract number / Numéro de contrat	Please fill system information
Contract date:	
Machine customer name:	P2
Assign to:	RelR
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 550 HR3 / M2051dC 0.1111
SN:WA:	ASO089565_42.2331
Origin BST France order:	222010B
Installation date of material:	2022/11/03

TECHNICAL DATAS

PC MODEL	OptiPlex 7090
PC NAME	Tubescan422331
ADDITIONAL CAMERA INFO	TubeScan DS 550 HR3 / M2051dC 0.1111
OPERATION SYSTEM	Windows 10 Pro / v21H1
MEMORY RAM	16 GB
FREE SPACE ON C	131 / 237 GB
FREE SPACE ON D	E:\ 299 / 953 GB
TEAMVIEWER ID	1 033 132 474 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic
ORIGINAL VERSION	7.4.61.23532
UPGRADE OR DOWNGRADE VERSION LAST INTERVENTION	7.4.64.29287 from E2210
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	26/11/2024 08:30
End time PM:	26/11/2024 14:00

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1920X1080	Encoder wheel status	✓	Roue codeuse Changer
View monitor resolution		1920X1080	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✗	
PC's fans ?	✓		Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommend to exchange every 5 years.
PC's filter	⏸		Installation date:		2022-11-03 -> 02 YEAR(S)
Lens cleaning	✓		UPS communication?	⏸	
Mirror cleaning	⏸		Software workflow communication	✓	
Backing or RRB cleaning	✓		Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100% camera	⏸	
Camera alignment with printing	✓		Operators instruction ?	✓	Quelques explications sur les réglages faites.
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
		Réglage fait léger			

Kisspoint only with 2 cameras  | décalage entre les 2. |

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

- : Checked, nothing to report / Vérifié, RAS
: Not OK, checked comment / Pas OK, vérifiez commentaires
: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :


28/11/2024 15:12


28/11/2024 15:09