

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Etik Ouest ACU231796 Mm Julien AUBRON ZA, Route des Borgnières 85300 Soullans France +33 2 51 49 17 27 jaubron@etikouest.com
--	---

Preventive reference number	PMREPORT-326_PM965_2025-09-16
Contract number / Numéro de contrat	CM2105039
Contract date:	2021/10/01 -> 2024/09/30
Machine customer name:	Venus
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 430 4K / M2089aC-0.1111
SN:WA:	ASO081814_42.2031
Origin BST France order:	212464
Installation date of material:	2022/01/26

TECHNICAL DATAS

PC MODEL	OptiPlex 7090
PC NAME	TubeScan422031
ADDITIONAL CAMERA INFO	TubeScan DS 430 4K / M2089aC-0.1111
OPERATION SYSTEM	Windows 10 Pro / v22H2
MEMORY RAM	16 GB
FREE SPACE ON C	88.3 / 237 GB
FREE SPACE ON D	-
TEAMVIEWER ID	670 194 101 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic
ORIGINAL VERSION	7.2.81.120
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	16/09/2025 15:00
End time PM:	16/09/2025 17:00

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	
View monitor resolution		1920x1080	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓	CL cable modified (Terminal block)	Alarm indicator status ?	⏸	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✗	
PC's fans ?	✓		Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommand to exchange every 5 years.
PC's filter	⏸		Installation date:		2022-01-26 -> 03 YEAR(S)
Lens cleaning	✓		UPS communication?	⏸	
Mirror cleaning	✓		Softwareworkflowcommunication	⏸	
Backing or RRB cleaining	✓		Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100%camera	⏸	
Camera alignment with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓ ENCODER WHEEL:: 2RDHO234275
- ✓ LED Board equipped V40 L=140mm: 1ELLT256485
- ✓ LED Board equipped V40 L=160mm: 1ELLT256486
- ✓ ENCODER'S SPRING
- ✓ BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Done
- RBB must be replaced or minimum 1 roller (stuck)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :

17-Sep-25 11:59 AM

17-Sep-25 12:01 PM

ATTACHED PM'S FILE(S)

[Screenshot 16092025](#)

