

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	DS Smith (Contoire-Hamel) xxx M. Stéphane Ryckebusch 570 Rue national Contoire-Hamel 80500 Trois-Rivières France +33 7 88 98 25 49 stephane.ryckebusch@dssmith.com
--	---

Preventive reference number	PMREPORT-193_PM787_2024-12-19
Contract number / Numéro de contrat	CM2012036
Contract date:	2021/12/01 -> 2024/11/30
Machine customer name:	Cobden Chadwick
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO092491_WA0021320
Installation date of material:	2023/02/06

CUSTOMER ORDER:	CDE CLIENT M3 2014263
-----------------	-----------------------

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE04.2-7-A
PC NAME	21320-IPQ-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 pro
MEMORY RAM	64 gb
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	1 649 168 535
IP ADDRESS EXTERN FOR INTERNET	192.168.1.21
ORIGINAL VERSION	
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	19/12/2024 08:30
End time PM:	19/12/2024 14:30

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	⏸	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	
Digitalcheckfan	✗	Il manque une embase pour le filtre de la camera 3	Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2023-02-06
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✗	Carte HS necessite une intervention pour remplacement de carte, flash bulb et calibration	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtu		8.6
Camerachangefiltercheckfan	✓		Softwareipqwsc		no
Traversewscamerashadowreducingbackplate	⏸		Softwareipqpps		no
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		no
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✗	
Traversewscameracalibrationzoomirisfocus	✗		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓	Prevoir arret de & heure lors de l'intervention de Janvier pour refaire la calibration des cam2 et 3			

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name:


Date :

BS

Name:

Date :


19/12/2024 15:45


19/12/2024 15:46

ATTACHED PM'S FILE(S)

Offre PR 241122-0237	CDE CLIENT M3 2014263
	