

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Adhex Technologies 231128 M. Franck Leborne 44 Rue de Longvic 21300 Chenôve France +33 6 21 31 68 54 f.leborne@adhex.com
--	---

Preventive reference number	PMREPORT-310_PM949_2025-07-21
Contract number / Numéro de contrat	CM1911023
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	E5
Assign to:	RelR
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 330 HR1 / M2051dC 0.1388
SN:WA:	ASO099024_50.2682
Origin BST France order:	232217
Installation date of material:	2023/10/09

TECHNICAL DATAS

PC MODEL	OptiPlex 3090 / Tag GFYL6S3
PC NAME	TubeScan502682
ADDITIONAL CAMERA INFO	TubeScan DS 330 HR1 / M2051dC 0.1388
OPERATION SYSTEM	Windows 10 Pro / v21H2
MEMORY RAM	16 GB
FREE SPACE ON C	126 / 235 GB
FREE SPACE ON D	-
TEAMVIEWER ID	1 998 120 144 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic - Pas de câble RJ45
ORIGINAL VERSION	7.4.55.19495
UPG OR DNG VERSION DURING MAINTENANCE	7.4.66.32550

Start time PM:	21/07/2025 13:15
End time PM:	21/07/2025 14:30

		COMMENTS			COMMENTS
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	
View monitor resolution		1920x1080	Encoder wheel on web?	✓	Running on roller not on web.
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓	Ok be careful with 24V transfo for Tubescan was not plugged properly.	Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	⏸	
PC's fans ?	✓		Date UPS's batteries exchanged ?		2023/09/01
PC's filter	⏸		Installation date:		2023-10-09 -> 01 YEAR(S)
Lens cleaning	✓		UPS communication?	✓	power input/output 234V
Mirror cleaning	⏸		Software workflow communication	⏸	
Backing or RRB cleaining	✓		Check Teamviewer access	⏸	No cable for remote
Lens Focal	✓		Calibration of camera detail & 100% camera	⏸	
Camera alignment with printing	⏸		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	⏸	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	⏸	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

- ✅: Checked, nothing to report / Vérifié, RAS
❌: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :


23/07/2025 10:41


23/07/2025 10:42