

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	RKW Saint Freres Emballage S.A.S 231801 M. Stéphane Szczypa Rue Marius Sire 80420 Ville Le Marclet France +33 3 22 39 49 00 / +33 7 64 40 00 65 stephane.szczypa@rkw-group.com
--	---

Preventive reference number	PMREPORT-240_PM846_2025-03-19
Contract number / Numéro de contrat	CM2411068
Contract date:	2025/01/01 -> 2027/12/31
Machine customer name:	136
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO086207_WA0021967
Installation date of material:	2024/03/15

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE04.0-5-A industrial PC High Speed 3ELEC445635 9556000295 BST GmbH
PC NAME	21967iPQ-Center1-
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Entreprise LTSC / 2018
MEMORY RAM	96 GB
FREE SPACE ON C	31.9/75.0 GB
FREE SPACE ON D	96.5/97.5 GB
TEAMVIEWER ID	560 655 312 / v15
IP ADDRESS EXTERN FOR INTERNET	IP Address : 10.231.20.2 Subnet Mask : 255.255.0.0 Default Gateway : 10.231.1.1
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	18/03/2025 14:18
End time PM:	

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✓	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2024-03-15 -> 01 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	⏸	Pas de disponibilité, machine en production.	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		.
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		.
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqli		.
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✗	
Traversewscameracalibrationzoomirisfocus	⏸	Pas de disponibilité, machine en production.	Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	⏸	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:


Name: **M. Stéphane Szczypa**


Date :

BST eltromat FRANCE signature:

Name: **Coutellier Vivien**

Date :


19/03/2025 14:21


20/03/2025 09:38