

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Adhex Technologies 231128 M. Franck Leborne 44 Rue de Longvic 21300 Chenôve France +33 6 21 31 68 54 f.leborne@adhex.com
--	---

Preventive reference number	PMREPORT-217_PM823_2025-02-17
Contract number / Numéro de contrat	CM1911023
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	M4150
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 430 CP / 318x-0.1944
SN:WA:	34.472
Installation date of material:	

TECHNICAL DATAS

PC MODEL	OptiPlex 3040 / Tag 970NZC2
PC NAME	TubeScan34472
ADDITIONAL CAMERA INFO	TubeScan DS 430 CP / 318x-0.1944
OPERATION SYSTEM	Windows 10 Pro / v20H2
MEMORY RAM	8 GB
FREE SPACE ON C	403 / 453 GB
FREE SPACE ON D	-
TEAMVIEWER ID	841 892 203 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic / Pas de câble RJ45
ORIGINAL VERSION	7.0.52.96
UPG OR DNG VERSION DURING MAINTENANCE	7.0.54.113

Start time PM:	17/02/2025 15:30
End time PM:	17/02/2025 17:30

		COMMENTS			COMMENTS
Touch monitor calibration	✗	Touch Screen doesn't work	Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	
View monitor resolution		1680x1050	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✗	Defect Output only
Connectors cameras (well tight?)	✓				
PC's fans ?	⏸				
PC's filter	⏸		Installation date:		
Lens cleaning	✓	Looking up			
Mirror cleaning	✓		Softwareworkflowcommunication	⏸	
Backing or RRB cleaining	✓		Check Teamviewer access	✓	Via dongle wifi USB / ID 841 892 203
Lens Focal	✓		Calibration of camera detail & 100%camera	⏸	
Camera alignment with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓ ENCODER WHEEL:: 2RDHO234275
- ✓ LED Board equipped V40 L=140mm: 1ELLT256485
- ✓ LED Board equipped V40 L=160mm: 1ELLT256486
- ✓ ENCODER'S SPRING
- ✓ BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Done. Light Tower bulded from another source. Touch Screen doesn't work.

Customer signature:

Name:

Date :


lundi 17 février 2025 17:18:36

BST eltromat FRANCE signature:

Name:

Date :


lundi 17 février 2025 17:18:51

ATTACHED PM'S FILE(S)

Picture 17022025	Screenshot 17022025
	