

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Adhex Technologies 231128 M. Franck Leborne 44 Rue de Longvic 21300 Chenôve France +33 6 21 31 68 54 f.leborne@adhex.com
--	---

Preventive reference number	PMREPORT-314_PM952_2025-07-22
Contract number / Numéro de contrat	CM1911023
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	BOB.19
Assign to:	RelR
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 250 4K / M2089aC0.0833
SN:WA:	ASO093905_42.2109
Origin BST France order:	212586
Installation date of material:	2022/03/21

TECHNICAL DATAS

PC MODEL	OptiPlex 7090 / Tag 2Y420L3
PC NAME	TubeScan422109
ADDITIONAL CAMERA INFO	TubeScan DS 250 4K / M2089aC0.0833
OPERATION SYSTEM	Windows 10 Professionnel / v21H1
MEMORY RAM	16 GB
FREE SPACE ON C	126 / 237 GB
FREE SPACE ON D	-
TEAMVIEWER ID	917 616 080 / v15
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.57.20297
UPGRADE OR DOWNGRADE VERSION LAST INTERVENTION	7.4.67.34209 from E2569
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	22/07/2025 10:15
End time PM:	22/07/2025 11:00

COMMENTS			COMMENTS		
Touch monitor calibration	II		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	
View monitor resolution		1920x1080	Encoder wheel on web?	✓	No but wheel is notched adn everything is stable.
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓	USB Cable from camera has been changed.	Alarm indicator status ?	✓	No alarm only I/O.
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	II	
PC's fans ?	✓		Date UPS's batteries exchanged ?		2022/03/01
PC's filter	II		Installation date:		2022-03-21 -> 03 YEAR(S)
Lens cleaning	✓		UPS communication?	✓	Communication OK but battery warning on. 236V
Mirror cleaning	✓		Softwareworkflowcommunication	✓	Qlink
Backing or RRB cleaining	✓		Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100%camera	II	
Camera alignment with printing	✓		Operators instruction ?	II	
Check web under camera	✓		Screenshots	II	
Height compensator calib	✓		ACRONIS ?	II	
Encoder offset calib	✓		Backup application	II	
Only with EV- LED calibrations	II				

Kisspoint only with 2 cameras



Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

- ☒: Checked, nothing to report / Vérifié, RAS
☒: Not OK, checked comment / Pas OK, vérifiez commentaires
☐: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :


23/07/2025 10:38


23/07/2025 10:38