

On Customer Site

Visit Report

Reference :

Commande BSTe France :		Call : E1334	
Customer :	CCL TABAC	System :	TubeScan DS 550 4000
Customer Contact :	NINA	SN :	ASO090409-42.2359
Customer Order number :		Machine Nickname :	S27

Visit Purpose :

Mechanical Preparation	☒	Installation	☒	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	07/10/2022					
Travel To	1h20					
Start Time	10h00					
Lunch Time	1h					
End Time	16h00					
Travel From	1h20					

Details	Installation de Tubescan sur ROTOCONTROL S27
---------	--

Purpose of the visit completed : Yes ☐ No ☒

Need a new visit : Yes ☒ No ☐

On Customer Site

Maintenance Checklist for NYQUIST Systems

Customer name and place : CCL Chilly TABAC

Contact person at customer : NINA

Customer Mail & Mobile/Landline :

System Type : DS550 4000 M2032aC 0.1388

SN : ASO090409-42.2359

Machine Manufacturer/Model/Nickname : ROTOCONTROL

Date : 07102022

Name : JEAN BAPTISTE NGUYEN

Comments :

not connected to the Rotocontrol. Need camera-symbol
on Rotocontrol screen.

Signatures :



BST eltromat FSE

Customer

On Customer Site

Technical datas

Computer name : [TubeScan422359](#)

Total Physical Memory : [16 GB](#)

Free Space in C Drive (System) : [152 GB](#)

OS : [Win 10 Pro / v21H1](#)

Screen Resolution Touch : [1024x768](#)

Screen Resolution Full View : [1920X1080](#)

Computer Model : [OPTIPLEX 7090](#)

Date : [2022](#)

Software : [7.4.25.71](#)

Remote Maintenance (Teamviewer) [1 074 214 774](#)

IP address : [DHCP](#)

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [916 669 771 / v15](#)

On Customer Site

Notes
