

On Customer Site

Visit Report

Reference :

Commande BSTe France : 222324/ AQ0016023		Commande BSTe Int. : E1446	
Customer :	SBE	System :	TubeScan DS 330 4000
Customer Contact :	M. Nicolas Robert	SN :	ASO091667_50.2397
Customer Order number :	CDE CLIENT BPA 090922	Machine Nickname	MPS 8

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☒	Under Warranty	☒	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	05/01/2023					
Travel To	4					
Start Time	11h40					
Lunch Time	1					
End Time	17h40					
Travel From	4					

Details	The bearing of one roll on the tubescan on the MPS 11 is dead and need a replacement.
---------	---

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Customer details for NYQUIST Systems

Customer name and place : [SBE / 17 rue Théodore Botrel, 35550 Pipriac - France](#)

Contact person at customer : [M. Nicolas Robert \(Coordinateur Flexo\)](#)

Customer Mail & Mobile/Landline : atelier.flexo@sbe-etiquettes.fr / +33 2 99 34 37 49

System Type : [DS 330 4000 / M2032aC 0.833](#)

SN : [50.2397](#)


Machine Manufacturer/Model/Nickname : [MPS / EF330 H205 / MPS 8](#)

Date : 05/01/2023

Name : [M. Vivien Coutellier](#)

Comments :

Signatures :



Robert Nicolas 2023-03-03T12:00:19+01:00

BST eltromat FSE

Customer

On Customer Site

Technical datas

Computer name : [TubeScan502397](#)

Total Physical Memory : [16GB](#)

Free Space in C Drive (System) : [132GB](#)

OS : [Windows 10 Pro](#)

Screen Resolution Touch : [1024X768 \(Touch\)](#)

Screen Resolution Full View : [1920X1080](#)

Computer Model : [Optiplex 7090](#)

Remote Maintenance (Teamviewer)

IP address : [192.168.0.9](#)

Subnet mask : [255.255.255.0](#)

Default gateway : [192.168.0.75](#)

Preferred DNS server : [8.8.8.8](#)

Alternate DNS server :

Teamviewer ID / Version : [429 903 817/ v15](#)

On Customer Site

Notes
