

On Customer Site

Visit Report

Reference :

Commande BSTe France :		Call : E1266	
Customer :	Valetiq	System :	TubeScan DS 330 HR1
Customer Contact :	M. Arthur Caniau	SN :	42.2240 / ASO087507
Customer Order number :	222143	Machine Nickname :	KDO2

Visit Purpose :

Mechanical Preparation	☐	Installation	☒	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	27/07/2022	03/08/2022			
Travel To	0.5	0.5			
Start Time	9h00	08h30			
Lunch Time	0.5	0.5			
End Time	13h00	13h30			
Travel From	0	0			

Details	Installation et mise en service du TubeScan
---------	---

Purpose of the visit completed : Yes ☐ No ☒

Need a new visit : Yes ☒ No ☐

On Customer Site

Customer Details for NYQUIST Systems

Customer name and place : [Valetiq, rue Berthelot, 59860 Bruay-sur-l'Escaut – France](#)

Contact person at customer : [M. Arthur Caniau \(Responsable Technique\)](#)

Customer Mail & Mobile/Landline : Arthur.caniau@valetiq.com / +33 3 27 30 97 92 / +33 6 88 82 60 86

System Type : [TubeScan DS 330 HR1 / M2051C-0.1388](#)

SN : [42.2240](#)

Machine Manufacturer/Model/Nickname : [KDO2](#)


Date : [04/08/2022](#)

Name : [Richard Relin](#)

Signatures :

BST eltromat FSE

Customer



Richard Relin 2022-08-04T13:03:04+02:00



Arthur Caniau 2022-08-04T12:44:06+02:00

On Customer Site

Technical datas

Computer name : [Tubescan422240](#)

Total Physical Memory : [8 GB](#)

Free Space in C Drive (System) : [165 GB](#)

OS : [Win 10 Pro](#)

Screen Resolution Touch : [1024x768](#)

Screen Resolution Full View : [2560x1440](#)

Computer Model : [Optiplex 7090](#)

Date : [2022](#)

Version : [7.4.16.36](#)

Remote Maintenance (Teamviewer)

IP address :

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [584 979 431/ v12](#)

On Customer Site

Notes
