

On Customer Site

Visit Report

Reference :

Commande BSTe France : AQ00010446 V4		Call : E1242	
Customer :	Livcer	System :	TubeScan DS 550 4K
Customer Contact :	M. Christophe Bourgau	SN :	42.2249
Customer Order number :	222010A	Machine Nickname :	Phoenix

Visit Purpose :

Mechanical Preparation	☒	Installation	☒	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	4/07/2022	05/07/2022	06/07/2022	07/07/2022	
Travel To	2.0	0.5	0.5	0.5	
Start Time	10h00	8h30	8h30	8h30	
Lunch Time	0.5	0.5	0.5	0.5	
End Time	18h00	18h00	18h00	16h00	
Travel From	0.5	0.5	0.5	2.0	

Details	Installation mécanique et mise en service du TubeScan ; Manque reseau pour Qlink
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Customer Details for NYQUIST Systems

Customer name and place : [Livcer 593 Avenue Blaise Pascal, Moissy-Cramayel 77550](#)

Contact person at customer. [M. Christophe Bourgau](#)

Customer Mail & Mobile/Landline. Christophe.bourgau@livcer.com / 07.56.21.33.64

System Type : [TubeScan DS 550 4K](#)

SN : [42.2249](#)

Machine Manufacturer/Model/Nickname : [Dcm Serval 850](#)

Date : [07/07/2022](#)

Name : [Richard Relin](#)


Signatures :

BST eltromat FSE

Customer



Richard Relin 2022-07-07T17:07:16+02:00



Christophe brougau2022-07-07T17:05:01+02:00

On Customer Site

Technical datas

Computer name : [Tubescan422249](#)

Total Physical Memory : [16 GB](#)

Free Space in C Drive (System) : [148 GB](#)

OS : [Win 10 Pro](#)

Screen Resolution Touch : [1024x768](#)

Screen Resolution Full View : [2560x1440](#)

Computer Model : [Optiplex 7090](#)

Date : [2022](#)

Version : [7.4.17.37](#)

Remote Maintenance (Teamviewer)

IP address :

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [/v12](#)

On Customer Site

Notes
