

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Jacquelin Frère Millésime xxxxx M. Nicolas Moreau 2 rue Jacques Germain 21420 Savigny-lès-Beaune France +33 3 80 25 06 56 planning.nicolas@jacquelin.fr
---	---

Ticket number:	E1956
Customer order:	BPA du 05022024
Machine customer name:	N° 1
Tiket type:	INTERVENTION
Assign to:	CouV -> vivien.Coutellier@bst.group
Ticket date:	2024/02/05
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 430 HR1 / M2051C-0.1944
SN:WA:	ASO075412_42.1736
Installation date of material:	2021/05/19
Teamviewer:	1 008 601 034 / v12
PC model:	Optiplex 3080
Original Application Version	7.2.80.119

1 day(s) of intervention calculation

2024 / 2024	Thu.08/02
Drive time	0.5
AM Start	09:00
AM End	12:00
PM Start	12:15
PM End	14:30
Drive time	3.5

Start date of visite	2024/02/08-09:00
End date of visite	2024/02/08-14:30
Reason:	boot issue - windows had been reset. new installation of windows...
Actions:	need reinstall new image and backup or intervention
Remarks:	The hard drive was replaced with a new image. The image of all the other nsystem was done also


Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name:


Date :



BST eltromat FRANCE signature:

Name:

Date :



ATTACHED CALL'S FILE(S)

[BPA du 05022024](#)

