

On Customer Site

Visit Report

Reference :

Commande BSTe France : SERV220204DT		Call : E1178	
Customer :	Reynders	System :	TubeScan DS 330 HR1
Customer Contact :	M. Augustynen Rudy	SN :	44.2091
Customer Order number :	SERV220204DT	Machine Nickname :	ABG/DIGICON/82

Visit Purpose :

Mechanical Preparation	☐	Installation	☒	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	04/05/2022	05/05/2022	06/ 05 /2022			
Travel To	0	0.5	0.5			
Start Time	14h00	9h00	8h45			
Lunch Time	0.5	0	0			
End Time	19h00	18h00	12h00			
Travel From	0.5	0	5.0			

Details	Commissioning for Tubescan and training operators.
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Customer Details for NYQUIST Systems

Customer name and place : [Reynders Nijverheidsstraat 3, 2530 Boechout, Belgique](#)

Contact person at customer. [M. Augustynen Rudy \(Technical service\)](#)

Customer Mail & Mobile/Landline. tsch@reynders.com/ 003234601446

System Type : [TubeScan DS 330 HR1](#)

SN : [44.2067](#)

Machine Manufacturer/Model/Nickname : [ABG/DIGICON/82](#)

Date : [06/05/2022](#)

Name : [Richard Relin](#)


Signatures :

BST eltromat FSE

Customer



Richard Relin 2022-05-06T10:57:35+02:00



Rudy Augustynen2022-05-06T10:57:20+02:00

On Customer Site

Technical datas

Computer name : [Tubescan442067](#)

Total Physical Memory : [8 GB](#)

Free Space in C Drive (System) : [181 GB](#)

OS : [Win 10 PRO](#)

Screen Resolution Touch : [1024x768](#)

Screen Resolution Full View : [2560x1440](#)

Computer Model : [Optiplex 7050](#)

Date : [2022](#)

Version : [7.4.13.33](#)

Remote Maintenance (Teamviewer)

IP address :

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [829589864 / v12](#)

On Customer Site

Notes
