

On Customer Site

Visit Report

Reference :

Commande BSTe France : INT230309 (Visite 3)		Call : E1578	
Customer :	CCL Chilly - Pharma	System :	TubeScan
Customer Contact :	M. Bruno Moreau	SN / WA :	
Customer Order number :		Machine Nickname :	

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	20 / 03 / 2023	/ /	/ /	/ /	/ /	/ /
Travel To	X					
Start Time	14h					
Lunch Time	X					
End Time	19h30					
Travel From	X					

Details	
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

NYQUIST System Instruction

Customer name and place : [CCL Package Label / 20 Avenue Arago – 91380 – Chilly-Mazarin - France](#)

Contact person at customer : [M. Bruno Moreau \(Operation Manager\)](#)

Customer Mail & Mobile/Landline : bmoreau@cclind.com / +33 7 63 94 28 08

System Type : [TubeScan](#)

Date : [20/03/2023](#)

Name : [M. Vivien Coutellier](#)

Comments :

Signatures :

A handwritten signature in black ink, consisting of a stylized 'B' and 'E'.

BST eltromat FSE

A large, stylized handwritten signature in black ink, consisting of several sweeping, interconnected loops.

Customer

On Customer Site

Notes

[Attirez l'attention du lecteur avec une citation dans le document, ou utilisez cet espace pour mettre en valeur un point clé. Pour placer cette zone de texte n'importe où sur la page, faites-la simplement glisser.]