

On Customer Site

Visit Report

Reference :

Commande BSTe France :		Commande BSTe Int. :	
Customer :	Adhex Technologies (Slovakia)	System :	TubeScan DS 330 HR1
Customer Contact :	M. Benjamin Gauthier	SN :	ASO09458-50.2591
Customer Order number :		Machine Nickname	Saturn

Visit Purpose :

Mechanical Preparation	☒	Installation	☒	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☒	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	04/09/2023	05/09/2023	06/09/2023	07/09/2023		
Travel To	8	0.25	0.25	0.25		
Start Time	13h00	7h45	8h45	8H15		
Lunch Time	1	1	1	1		
End Time	15h30	16h00	16h00	12h00		
Travel From	0.25	0.25	0.25	10		

Details	Startup and instructions for the system tubescan 5.2491 on the Prati Saturn
---------	---

Purpose of the visit completed: Yes ☒ No ☐

Need a new visit: Yes ☐ No ☒

On Customer Site

Customer details for NYQUIST Systems

Customer name and place :

Client Name	Adhex Technologies (Slovakia)
Address	Pol'ná Ulica 9
Zip	90301
City	Senec
Country	Slovaquie

Contact person at customer :

CONTACT 1 M. Benjamin Gauthier

Customer Mail & Mobile/Landline :

PHONE 1	<u>+421 245 650 641</u>
EMAIL 1	<u>b.gauthier@adhex.com</u>

System Type :

System Type	TubeScan DS 330 HR1 /
-------------	-----------------------

SN : 42.2358

Machine Manufacturer/Model/Nickname :

Machine type	Rewinder Prati / Saturn
--------------	-------------------------


Date : 07/09/2023

Name : M. Vivien Coutellier

Signatures :



BST eltromat FSE



Customer

On Customer Site

Technical datas

Computer name : [TubeScqn502491](#)

Total Physical Memory :

Free Space in C Drive (System) : [135gb](#)

OS : [Windows 10 Pro](#)

Screen Resolution Touch : [720p \(Touch\)](#)

Screen Resolution Full View : [1080p](#)

Computer Model : [Optiplex 3090](#)

Remote Maintenance (Teamviewer)

IP address : [TBD](#)

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [/v15](#)

On Customer Site

Notes
