

On Customer Site

Visit Report

Reference :

Commande BSTe France :		Call / PM number : E1253	
Customer :	Ds Smith Contoire	System :	iPQ View
Customer Contact :	M. Dylan Tyteca	ASO / WA :	WA0021320/ASO070985
Customer Order number :	SERV220722	Machine Nickname :	Kobden Chadwick

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☒	Under Warranty	☐	Out of Warranty	☒
Instruction	☐ Yes				
	☒ No				

	01 / 08 / 2022	/ /	/ /	/ /	/ /	/ /
Travel To	3h00					
Start Time	12h00					
Lunch Time	0.5					
End Time	13h30					
Travel From	3h00					

Details	Changement roulements de la camera matricielle. -
---------	--

Purpose of the visit completed : Yes ☐ No ☒

Need a new visit : Yes ☒ No ☐

On Customer Site

Customer details for iPQ systems

Customer name and place : [DS Smith • 39 Rue Nationale, 80500 Contoire-Hamel](#)

Contact person at customer : [M. Dylan Tyteca \(Responsable Atelier Pré-impression\)](#)

Customer Mail & Mobile/Landline : Dylan.tyteca@dssmith.com / +33 6 86 15 54 16

System Type : iPQ View WA/ASO : [WA0021320/ASO070985](#)


Machine Manufacturer/Model/Nickname : [Cobden Chadwick](#)

Date : [01/08/2022](#)

Name : [Richard Relin](#)

Comments :

Signatures :



Richard Relin 2022-08-01T13:54:14+02:00

BST eltromat FSE



Dylan Tyteca 2022-08-01T13:54:00+02:00

Customer

On Customer Site

Notes
