

On Customer Site

Visit Report

Reference :

Commande BSTe France :		Commande BSTe Int. : E1318	
Customer :	Label Products	System :	TubeScan DS430
Customer Contact :	M. Matthias Dhondt	SN :	42.2327
Customer Order number :		Machine Nickname :	Venus

Visit Purpose :

Mechanical Preparation	☒	Installation	☐	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	27 /09/ 2022					
Travel To	4.5					
Start Time	13h30					
Lunch Time	0.5					
End Time	18h00					
Travel From	4.5					

Details	Upgrade System.
---------	-----------------

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for NYQUIST Systems

Customer name and place : [Vichtseweg 176/A, 8790 Waregem, Belgique](#)

Contact person at customer : [M. Mathias Dhondt](#)

Customer Mail & Mobile/Landline : [+32 56 77 22 40](#)

System Type : [DS430](#)

SN : [42.2327](#)

Machine Manufacturer/Model/Nickname : [Venus](#)

Date : [27/09/2022](#)

Name : [Richard Relin](#)

Comments :

Signatures :



Richard Relin 2022-09-27T17:41:28+02:00

BSF eltromat FSE

AGEPA
Kaiserbaracke 166 • B-4780 ST.VITH
Tel. +32.80.86.29.83 • Fax +32.80.86.28.21
mailbox@agepa.com • www.agepa.com

Mathias Dhondt 2022-09-27T17:41:08+02:00

Customer

On Customer Site

Technical datas

Computer name : [Tubescan422327](#)

Total Physical Memory : [8 GB](#)

Free Space in C Drive (System) : [183GB](#)

OS : [Windows 10 Pro](#)

Screen Resolution Touch : [1024X768](#)

Screen Resolution Full View : [1920X1080](#)

Computer Model : [OPTIPLEX 3080](#)

Date : [2022](#)

Remote Maintenance (Teamviewer)

IP address : DHCP

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [1 028 165 045 / v15](#)

On Customer Site

Notes
