

On Customer Site

Visit Report

Reference :

Commande BSTe France : INT 210623		Commande BSTe Int. : E837	
Customer :	CCL Package Label	System :	TubeScan DS 430 4K
Customer Contact :	M. Jean-Charles Campana	SN :	42.1585 / ASO071778
Customer Order number :	110069	Machine Nickname :	G281

Visit Purpose :

Mechanical Preparation	☒	Installation	☒	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	06/07/2021					
Travel To	0.5					
Start Time	9h00					
Lunch Time	0.5					
End Time	13h30					
Travel From	0					

Details	Préparation mécanique. Installation du système TubeScan. Configuration et backup du système.
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Customer Details for NYQUIST Systems

Customer name and place : [CCL Package Label / 20 Avenue Arago – 91380 – Chilly-Mazarin - France](#)

Contact person at customer : [M. Jean-Charles Campana \(Responsable de Production\)](#)

Customer Mail & Mobile/Landline : jccampana@cclind.com / +33 7 63 04 72 66

System Type : [TubeScan DS 430 4K / M2089aC0.1111](#)

SN : [42.1585 / ASO071778](#)

Machine Manufacturer/Model/Nickname : [Gallus / EM 280 / Presse G281](#)

Date : [06/07/2021](#)


Name : [Richard Relin](#)

Comments :

Signatures :



Richard Relin 2021-07-06T16:41:52+02:00



Fabrice Benard 2021-07-06T16:41:33+02:00

BST eltromat FSE

Customer

On Customer Site

Technical datas

Computer name : [TubeScan421585](#)

Total Physical Memory : [16 GB](#)

Free Space in C Drive (System) : [164 GB](#)

OS : [Win 10 PRO](#)

Screen Resolution Touch : [1024x768](#)

Screen Resolution Full View : [1920x1080](#)

Computer Model : [D11S](#) .

Date : [2020](#)

Version : [7.2.55.84](#)

Remote Maintenance (Teamviewer)

IP address : [DHCP Auto](#)

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [631 030 314 / v12](#)

On Customer Site

Notes
