

On Customer Site

Visit Report

Reference :

Commande BSTe France :		Call / PM number : E1678/1679	
Customer :	MCC (Sautron)	System :	
Customer Contact :	M. Wiliam Breit	ASO / WA :	
Customer Order number :		Machine Nickname :	S7/9NGV

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☒	Under Warranty	☐	Out of Warranty	☒
Instruction	☐ Yes				
	☒ No				

	21 / 06 / 2023		/ /	/ /	/ /	/ /
Travel To	2.5					
Start Time	15h00					
Lunch Time	0					
End Time	18h00					
Travel From	5					

Details	Troubleshoot IPQ Check 7S ; Hub pour communication Illumination HS brancher en direct sur PC A commander. Troubleshoot 9NGV ; Problème MOROS branchement en direct DELL a Beckhoff.
---------	---

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Customer name and place : [MCC / Zi de Tournebride, R.D. 65 F, 44880 Sautron](#)

Contact person at customer / Title : [M. William Breit \(Responsable de production\)](#)

Customer Mail & Mobile/Landline : william.breit@mcclabel.com / +33 2 28 07 24 00

System Type : [iPQ Check](#)

Date : [21/06/2023](#)

Name : [Relin Richard](#)

Comments :

Signatures :



Richard Relin 2023-06-21T17:50:05+02:00



Matthieu Cabelguen 2023-06-21T17:49:55+02:00

BST eltromat FSE

Customer

On Customer Site

Notes
