

On Customer Site

Visit Report

Reference :

Commande BSTe France : NQ2012049014 / PR201208A70		Call : E663	
Customer :	CCL Package Label	System :	TubeScan DS 550 HR1
Customer Contact :		SN :	42.1631 / ASO073562
Customer Order number :	109740	Machine Nickname :	511/EMS 510

Visit Purpose :

Mechanical Preparation	☒	Installation	☒	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	07/01/2021	08/01/2021				
Travel To	2	0,5				
Start Time	09h30	9h00				
Lunch Time	0.5	0.5				
End Time	18h00	12h00				
Travel From	0,5	2				

Details	Préparation mécanique. Installation du système TubeScan. Configuration et backup du système.
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Customer Details for NYQUIST Systems

Customer name and place : CCL Package LABEL / RUE Denis Papin – 91380 – Chilly-Mazarin - France

Contact person at customer. MME BUEHLMANN Nina(Responsable de production)

Customer Mail & Mobile/Landline. Nbuehlmann@cclind.com/ +33 6 63 75 08 72

System Type : TubeScan DS 550 HR1 / M2051C-0.2222

SN : 42.1631 / ASO073562


Machine Manufacturer/Model/Nickname : 510/511EMS

Date : 08/01/2020

Name : Richard Relin

Comments :

Signatures :



Richard Relin 2021-01-08T12:26:01+01:00



BUEHLMANN NINA 2021-01-08T12:25:46+01:00

BST eltromat FSE

Customer

On Customer Site

Technical datas

Computer name : [TubeScan421631](#)

Total Physical Memory : [8 GB](#)

Free Space in C Drive (System) : [172 GB](#)

OS : [Win 10 PRO](#)

Screen Resolution Touch : [1024x768](#)

Screen Resolution Full View : [1920x1080](#)

Computer Model : [OPTIPLEX 3070 .](#)

Date : [2020](#)

Version : [7.2.41.68](#)

Remote Maintenance (Teamviewer)

IP address : [DHCP Auto](#)

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [/ v15](#)

On Customer Site

Notes
