

On Customer Site

Visit Report

Reference :

Commande BSTe France : INT221129 (Visite 2)		Call : E1416	
Customer :	CCL Chilly - Pharma	System :	TubeScan
Customer Contact :	M. Bruno Moreau	SN / WA :	
Customer Order number :		Machine Nickname :	

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	20 / 03 / 2023	/ /	/ /	/ /	/ /	/ /
Travel To	X					
Start Time	8h30					
Lunch Time	X					
End Time	12h30					
Travel From	X					

Details	
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

NYQUIST System Instruction

Customer name and place : [CCL Package Label / 20 Avenue Arago – 91380 – Chilly-Mazarin - France](#)

Contact person at customer : [M. Bruno Moreau \(Operation Manager\)](#)

Customer Mail & Mobile/Landline : bmoreau@cclind.com / +33 7 63 94 28 08


System Type : [TubeScan](#)

Date : [20/03/2023](#)


Name : [M. Vivien Coutellier](#)

Comments :

Signatures :



BST eltromat FSE



Customer

On Customer Site

Notes
