

On Customer Site

Visit Report

Reference :

Commande BSTe France : INT200724		Call / PM number : E560	
Customer :	Adhex Technologies	System :	Inspection System
Customer Contact :	M. Franck Leborne	SN :	207117
Customer Order number :		Machine Nickname :	Alpha

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☒	Under Warranty	☐	Out of Warranty	☒
Instruction	☐ Yes				
	☒ No				

	28 / 07 / 2020					
Travel To	0					
Start Time	14 :45					
Lunch Time	0					
End Time	17 :30					
Travel From	0					

Details	Camera replaced on inspection system + Calibration
---------	--

Purpose of the visit completed : Yes ☒ No ☐
 Need a new visit : Yes ☐ No ☒

On Customer Site

Customer details for NYQUIST Systems

Available supporting documents :

- Maintenance instruction for Digital Strobe & EagleView systems
- Check list for maintenance

Customer name and place : [Adhex Technologies / 44 Rue de Longvic – 21300 - Chenôve](#)

Contact person at customer : [M. Franck Leborne \(Process Manager\)](#)

Customer Mail & Mobile/Landline : f.leborne@adhexcom / +33 6 21 31 68 54

System Type :

SN : [207117](#)

Machine Manufacturer/Model/Nickname : [EDALE / ALPHA / ALPHA](#)

Date : [28/07/2020](#)

Name : [Arnaud Darcel](#)

Comments :

Signatures :



Arnaud Darcel 2020-07-28T17:36:09+02:00

BST eltromat FSE



Franck Leborne 2020-07-28T17:35:59+02:00

Customer

On Customer Site

Technical datas

Computer name : [Lccd-Press](#)

Total Physical Memory : [12 GB](#)

Free Space in C Drive (System) : [18.5 GB](#)

Free Space in D Drive : [373 GB](#)

OS : [Win 7](#)

Screen Resolution Touch : [1920x1080](#)

Computer Model : [95203445 / DX58SO2](#)

Date : [2011](#)

Remote Maintenance (Teamviewer)

IP address : [192.168.1.197](#)

Subnet mask : [255.255.255.0](#)

Default gateway : [192.168.1.253](#)

Preferred DNS server : [10.75.20.140](#)

Alternate DNS server : [8.8.8.8](#)

Teamviewer ID / Version : [891 243 787 / V7](#)

On Customer Site

Notes
