

On Customer Site

Visit Report

Reference :

Commande BSTe France : 212409/ASO080721		Call : E955	
Customer :	DB Technique (Olivet)	System :	TubeScan DS 180 HR1
Customer Contact :	M. Sylvain Grand	SN :	42.1752
Customer Order number :	1878	Machine Nickname :	Vega

Visit Purpose :

Mechanical Preparation	☒	Installation	☒	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	07/10/2021	08/10/2021				
Travel To	2h00	0.5				
Start Time	11h45	8h30				
Lunch Time	0.5	0.5				
End Time	18h30	13h00				
Travel From	0.5	2h00				

Details	Installation de Tubescan sur machine Smag Vega.
---------	---

Purpose of the visit completed : Yes ☒ No ☐
 Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for NYQUIST Systems

Customer name and place : [DB Technique / 547 rue de la Bergeresse, 45160 Olivet](#)

Contact person at customer : [M. Sylvain Grand \(Responsable Maintenance\)](#)

Customer Mail & Mobile/Landline : sylvain.grand@dbtechnique.fr / +33 6 20 50 04 08

System Type : [DS 180 HR1 /](#)

SN : [42.1966](#)

Machine Manufacturer/Model/Nickname : [SMAG / Vega / Vega](#)

Date : [04/11/2021](#)

Name : [Richard Relin](#)

Comments :

Signatures :



Richard Relin 2021-11-04T12:38:06+01:00

BST eltromat FSE



Sylvain Grand 2021-11-04T12:37:54+01:00

Customer

On Customer Site

Technical datas

Computer name : [TubeScan421966](#)

Total Physical Memory : [8 GB](#)

Free Space in C Drive (System) : [182 GB](#)

OS : [Win 10 Professionnel](#)

Screen Resolution Touch : [1024x768](#)

Screen Resolution Full View : [1920X1080](#)

Computer Model : [OPTIPLEX3080](#)

Date : [2021](#)

Remote Maintenance (Teamviewer)

IP address :

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [508629448 / v12](#)

On Customer Site

Notes
