

On Customer Site

## Visit Report

**Reference :**

|                                     |                              |                          |         |
|-------------------------------------|------------------------------|--------------------------|---------|
| Commande BSTe France : SERV211005DT |                              | Call / PM number : PM252 |         |
| Customer :                          | Soyaux Plastiques Complexage | System :                 | Jupiter |
| Customer Contact :                  | M. Thomas Roger              | SN :                     | 201647  |
| Customer Order number :             | BPA 11102021                 | Machine Nickname :       | FW1508  |

**Visit Purpose :**

|                        |                                        |                |                          |                 |                                     |
|------------------------|----------------------------------------|----------------|--------------------------|-----------------|-------------------------------------|
| Mechanical Preparation | <input type="checkbox"/>               | Installation   | <input type="checkbox"/> | Start-up        | <input type="checkbox"/>            |
| Maintenance            | <input checked="" type="checkbox"/>    | Under Contract | <input type="checkbox"/> | Out of Contract | <input checked="" type="checkbox"/> |
| Troubleshoot           | <input type="checkbox"/>               | Under Warranty | <input type="checkbox"/> | Out of Warranty | <input type="checkbox"/>            |
| Instruction            | <input type="checkbox"/> Yes           |                |                          |                 |                                     |
|                        | <input checked="" type="checkbox"/> No |                |                          |                 |                                     |

|             |               |  |  |  |  |  |
|-------------|---------------|--|--|--|--|--|
|             | 10 / 11 /2021 |  |  |  |  |  |
| Travel To   | 0.5           |  |  |  |  |  |
| Start Time  | 8h30          |  |  |  |  |  |
| Lunch Time  | 0             |  |  |  |  |  |
| End Time    | 11h00         |  |  |  |  |  |
| Travel From | 0             |  |  |  |  |  |

|         |                                                                                     |
|---------|-------------------------------------------------------------------------------------|
| Details | Maintenance Préventive du système d'inspection sur presse Comexi FW1508. Archivage. |
|---------|-------------------------------------------------------------------------------------|

Purpose of the visit completed :      Yes ☒      No ☐

Need a new visit :      Yes ☐      No ☒

*On Customer Site*

---

## Maintenance Checklist for AVT Systems

---

Customer name and place : [Soyaux Plastiques Complexages / Z.I La Croix Blanche – 16800 – Soyaux](#)

Contact person at customer : [M. Thomas Roger \(Responsible Site\)](#)

Customer Mail & Mobile/Landline : [t.roger@spcomplexages.fr](mailto:t.roger@spcomplexages.fr) / +33 5 45 38 37 11

SN : [201647](#)

Machine Manufacturer/Model/Nickname : [Comexi / FW1508 / FW1508](#)

Date : [10/11/2021](#)

Name : [Arnaud Darcel](#)

Comments :

**Signatures :**



Arnaud Darcel 2021-11-11T11:07:17+01:00

BST eltromat FSE

Customer

On Customer Site

### Prior to a Preventive Maintenance :

Check for system affecting modification reports and software releases.

Check for optional light source.

Check with customer about problems, or failure with the system.

#### 1. Cleaning the optical parts :

OK/NOK/NA

- Mirror cleaned wit ZEISS lens wipes. ☒☐☐
- Camera lens cleaned with ZEISS lens wipes. ☒☐☐
- Reflectors cleaned with soft cloth using iso propanol or alcohol. ☐☐☒
- Back plate cleaned. ☒☐☐
- Computer filter cleaned/~~replaced~~ ☒☐☐

#### 2. Camera calibration 100% :

OK/NOK/NA

- Field of View / Period ☐☐☒
- Offset/Gain Calibration. ☐☐☒
- Zero LED calibration : Anyspeed & Position ☐☐☒

#### 3. Check functioning of the Lamps :

OK/NOK/NA

- Lamps replacement. : ☐☐☒
- Brightness and uniformity of the image checked. ☒☐☐

#### 4. Replacement of the encoder wheel :

OK/NOK/NA

- Encoder wheel replaced and tightened ☐☐☒
- Spring replaced (if necessary) and spring force checked (ca. 1kg/10N) ☐☐☒

#### 5. Software update :

OK/NOK/NA

- Software Update (if necessary). ☐☒☐

Old SW version : [2.7.1](#)

New SW version : [2.7.1](#)

On Customer Site

---

### 6. Final check of the running system :

OK/NOK/NA

- Stability of live image checked (without reference image).
- Stripe alignment checked (Normal and reflective mode).
- Registration checked.
- Maximum speed checked.
- Hard drive capacity checked.
- Backup created and saved locally and/or on USB stick.

|                                     |                                     |                          |
|-------------------------------------|-------------------------------------|--------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

### 7. Backup :

OK/NOK/NA

- BackupRestore
- Archive Printflow

|                                     |                          |                          |
|-------------------------------------|--------------------------|--------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

### Parts replaced during Preventive Maintenance :

- |     |     |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

### Parts suggested to replace during the next Maintenance :

- |     |     |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

### Part need to be replaced as soon as possible :

- |     |     |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

On Customer Site

---

## Technical datas

---

Computer name : [AVT-PV-FW8](#)

Total Physical Memory : [1 GB](#)

Free Space in C Drive (System) : [5.02 GB](#)

Free Space in D Drive : [35.2 GB](#)

OS : [Microsoft Windows XP Professional 2002 – SP2](#)

Screen Resolution 1 : [1600x600](#)

Screen Resolution 1 : [1600x600](#)

Computer Model : [95203401 / IMBA-8650](#)

Date : [Aug, 2008](#)

ACB Firmware : [28/19](#)

### Remote Maintenance (Teamviewer)

IP address : [DHCP Automatic](#)

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [1 009 260 133 / v12](#)

*On Customer Site*

---

Notes

---